

INSPECTION REPORT


End of contract

GENERAL INFO

File	315719
License plate	1YEQ910
Vehicle identification number	TMBJJ7NX0LY038480
Dossier	2020035163
Make	Skoda Oct.Com.2.0TDI 110kW Amb
Mileage	80199
First registration	06/08/2020
client availability date	18/06/2026
inspectionDate	13/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
31	Front Bonnet // Smart Repair Small	N
66	Wing Front Left // Polish	Y
86	Door Front Left // Polish	Y
106	Door Rear Left // Polish	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	N
183	Wing Rear Right // Painting	N
205	Rocker Panel Right // Polish	Y
231	Wing Front right // Smart Repair Medium	N
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures




Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch




Door Rear Left // Polish-scratch



Door Front Left // Polish-scratch



Wing Front Left // Polish-scratch




Bumper Front // Smart Repair Large-scratch



Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Right // Polish-scratch



Wing Front right // Smart Repair Medium-dent



Front Bonnet // Smart Repair Small-scratch + dent



Bumper Rear // Painting-scratch + dent



Wing Rear Right // Painting-bad repair



Interior Cleaning // Small-stain