

## 2-DFF-314

2-DFF-314 · Move! 1.0 TSI 95cv 5v · 20 April 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-DFF-314	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ3PR088053
Model	Arona	Cylinder Capacity	999 <sup>cm<sup>3</sup></sup>
Model Versions	Move! 1.0 TSI 95cv 5v	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	01-03-2023
Color	Darkgrey	Odometer	71.747 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Darkgrey
KW	70	Number Headrests	5

# Images





## Accessories

ABS

Airbags

Alloy wheels

ASR

Audio System

Automatic air conditioning

Bluetooth car kit

Centre armrest

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Leather steering wheel

Navigation system

Parking sensors

Rear view camera

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	7 <sup>mm</sup>	Falken	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Rear Left	8 <sup>mm</sup>	Falken	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Front Right	7 <sup>mm</sup>	Falken	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Rear Right	8 <sup>mm</sup>	Falken	205 <sup>mm</sup>	60 <sup>mm</sup>	16 <sup>inch</sup>	All Season
Spare Tire Type	Compressor					

## Damages



Damage Part

Frontdoor - Left

Damage Type

Small dent(s)

Repair Type

Restyle

Acceptable

No



Damage Part

Fender - Rear Left

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Windscreen - Front

Damage Type

Chipped

Repair Type

Window Repair

Acceptable

No



Damage Part

Interior

Damage Type

Stains & dirt

Repair Type

Cleaning

Acceptable

No



Damage Part

Frontdoor - Right

Damage Type

Small dent(s)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Bumper - Rear

Damage Type

Small scratch(es)

Repair Type

Acceptable

Acceptable

Yes



Damage Part

spoiler RB

Damage Type

Small scratch(es)

Repair Type

Repair

Acceptable

No



Damage Part

Tailgate

Damage Type

Missing

Notes

wisserkapje

Repair Type Acceptable

Replace No



Damage Part

Trunkshelf

Damage Type

Missing

Repair Type

Replace

Acceptable

No