

» Overview

Order number: 1002320508
Order completed: 16.02.2026 16:13
Report number: 10056003
VIN: WVVZZZ3CZPE056105



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	EstateCar
Make:	Volkswagen
Model:	Passat
Manufacturers and type code:	0603 / CMM
Date of first registration:	19.04.2023
Mileage:	90,552 km
Proof of mileage:	ReadOff
Exterior colour:	Tornadorot
Roof colour:	Tornadorot
Propulsion:	Front
Fuel:	Diesel
Engine size (cc):	1,968 ccm
Performance:	90 kW (123 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining fabrics
Interior colour:	Titanschwarz/Titanschwarz/Titanschwarz
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	Yes
Registration certificate received:	No
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	29,100 KM

<p>"Business Premium" package incl. navigation system</p> <p>12-V outlet in center console rear and in luggage compartment</p> <p>2 beverage holders in front with cover</p> <p>2 USB-C ports in the front, 1 USB-C charging socket on the center console in rear, charging capacity up to 45 W</p> <p>230-V outlet in center console in rear</p> <p>3 head restraints in rear</p> <p>3-point seat belt for center rear seat</p> <p>3-point seat belts for outer rear seats</p> <p>3-point seat belts in front with height adjustment and seat belt pretensioners</p> <p>4 alloy wheels "Sepang" 6.5J x 16</p> <p>4-cylinder diesel engine 2.0 l</p> <p>4-cylinder diesel engine 2.0 l TDI, 90 kW</p> <p>7-speed automatic transmission or dual-clutch transmission DSG, note: PR family EDF</p> <p>8 speakers</p> <p>Adaptive Cruise Control ACC stop & go incl. speed limiter</p> <p>Air Care Climatronic 3 zone automatic climate control w/ allergen filter, enhanced air filter a. controls in rear</p> <p>Alternator 140 A</p> <p>Anti-theft alarm system</p> <p>Anti-theft alarm system with interior monitoring, backup horn, and towing protection</p> <p>App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto</p> <p>Aspherical exterior mirror on driver side</p> <p>Aut. headlight control w/ separate daytime running light, Leaving Home and manual Coming Home feature</p> <p>Auto-dimming interior rearview mirror</p> <p>Automatically-heated washer nozzles in front</p> <p>Autonomous Emergency Braking Front Assist (for Adaptive Cruise Control ACC up to 210 km/h)</p> <p>Basic equipment variant</p> <p>Battery 420 A (70 Ah)</p> <p>Black roof rails</p> <p>Body-colored lower side trims</p> <p>Bumpers with body-colored decorative trims</p> <p>Business</p> <p>Carpet mats in front and rear</p> <p>Carrier frequency 433.92 MHz-434.42 Mhz</p> <p>Category 0</p> <p>Child safety lock</p> <p>Chrome trims on the side windows</p> <p>Comfort seats in front</p> <p>Curtain airbag system for front and rear passengers incl. side airbags in front</p>	<p>Decorative inserts "Cross Hatch" for dashboard and door trim panels</p> <p>Decorative inserts "Piano Black" for center console</p> <p>Digital radio reception DAB+</p> <p>Disc brakes in front</p> <p>Disc brakes in rear</p> <p>Diversity antenna for FM reception</p> <p>Door and side trim panel in foam film and woven fabric</p> <p>Driver alert system</p> <p>Driver and front passenger airbag with front passenger airbag deactivation</p> <p>Driving on the right</p> <p>Dual-clutch transmission DSG DQ200</p> <p>Dynamic Road Sign Display</p> <p>Electric auxiliary air heater</p> <p>Electromechanical parking brake with Auto Hold function</p> <p>Electromechanical speed-sensitive power steering</p> <p>Electronic engine sound</p> <p>Electronic Stability Control and electromechanical brake booster</p> <p>Elimination of nameplate for engine designation on luggage compartment lid</p> <p>Emergency call service; no registration required, service is activated upon delivery</p> <p>Emission standard EU6 AP</p> <p>Equipment options subset for Germany</p> <p>Exterior mirrors, power-adjustable and heated, surround lighting, auto-dimming on driver side</p> <p>First aid kit, warning triangle and safety vest</p> <p>Folding luggage compartment floor</p> <p>Front center armrest, height- and longitudinally adjustable, w/ storage comp., 2 vents w/ chrome louvers in rear</p> <p>Front seats with height adjustment, ergoComfort seat on driver side, with electrical backrest adjustment</p> <p>Front vent and rotary light switch illuminated, with chrome bezel</p> <p>Front-wheel drive</p> <p>Fuel system for diesel engine</p> <p>Fuel tank with a volume of 66 l</p> <p>Gearshift knob in leather</p> <p>Green heat-insulating glass windows on sides and in rear</p> <p>Headlight range control</p> <p>Heated front seats</p> <p>Hill Start Assist</p> <p>Illuminated vanity mirror in sun visors, extractable sun visors</p> <p>Initial standard fuel filling</p> <p>Inserts of front seats and outer rear seats in fabric "Business"</p>
--	---

Instrument cluster with electronic speedometer, odometer and trip odometer, tachometer	Preparation for We Connect and We Connect Plus
Interior lights with switch-off delay and dimmer, 2 LED reading lights in front and 2 in rear	Proactive passenger protection system in combination with Front Assist
ISOFIX anchorage points for mounting 2 child seats on rear seats, also for i-Size child seats	Radio
Keyless Start with SAFELOCK	Rain sensor
Laminated safety glass windshield, heat- and sound-insulating	Rear exhaust tailpipe (standard)
Large navigation system M&I (Media & Internet package)	Rear fog light on one side, back-up light on both sides
Leather-wrapped multi-function steering wheel with shifting paddles	Rear shock absorption, basic version 1
LED entry/warning lights in front doors	Rear view camera system
LED front fog lamps and cornering light	Refrigerant R1234yf
LED headlamps with LED separate daytime running light	Regional code " ECE " for radio
LED light unit in front footwell	Remote unlocking for tailgate/trunk lid
LED rear combination lamps	Removable luggage compartment protective mat, back of rear bench seat backrest covered with black rubber
Left-hand drive	Right exterior mirror, convex
License plate carrier in front and rear (ECE)	Safety-optimized front head restraints, longitudinally and height adjustable
LongLife Service Regime	Semi-automated driving assistance TravelAssist and lane keeping system Lane Assist
Luggage compartment cover extractable and removable	Service indicator 30 000 km or 2 years (variable)
Luggage net	Shock absorption in front
Lumbar supports in front, power- adjustable on driver side, massage feature on driver side	Special identification label for EC for M1 passenger vehicles
Manual in German (Germany)	Standard battery/alternator capacity
Mass damper for steering wheel, 36 Hz	Standard climatic zones
Mistral Gray headliner	Standard engine starter
Mobile phone interface "Comfort" with inductive charging feature	Standard manufacturing sequence
Model update, week 45	Standard paint coating
Multi-color Digital Cockpit "Pro" selection of different info profiles possible	Standard pedal cluster
Multifunction camera	Standard wheel bolts
Navigation system "Discover Pro" incl. Streaming & Internet	Start-stop system with regenerative braking
Net partition	Suspension range 34 installation control only, no requirement forecast
No special edition	Tire Mobility Set: 12-volt compressor and tire sealant
No special purpose vehicle, standard equipment	Tire Pressure Monitoring System
Non-folding front passenger seat backrest	Tires 215/60 R16, rolling resistance class A
Non-smoker's package: Storage compartment and 12-V outlet in front	Tires without specification of tire brand
Not hot country	Tool kit and jack
Online service, with OCU, with head unit coding, without engine immobilizer interconnection	Transport protection film (minimum protection) with additional transport protection measures
Operating permit, alteration	Two-tone horn
Park Distance Control - warning signals for obstacles in the front and rear	Type approval country Germany
Part set without country-specific prescriptive standard	Unsplit rear bench seat, asymmetric folding backrest, center armrest with storage comp. and load-through hatch
Pedestrian monitoring	Vehicle class differentiation -3G0-
Plastic loading edge protection	Vehicles with special upgrade measures
Plastic scuff plates in door apertures	Voice control
Preparation for mobile key for vehicle access via smartphone	Wagon

Warning signal and warning light for front and rear seat belts
not fastened

Weight range 3 installation control only, no requirement
forecast

Wheelbase

Winter wheels (additional), 4 steel wheels 6.5J x 16, AirStop®
snow tires 215/60 R16 H, wheel trims

With electronic steering column lock

Without activated carbon canister with SCR

Without Adaptive Chassis Control

Without add. lights (interior lighting)

Without additional front underbody guard

Without alternative drive system

Without auxiliary heater/parking heater

Without CD/DVD for navigation

Without charging cable

Without child seat

Without clock

Without delivery equipment

Without differential lock

Without ECO function

Without electric motor (hybrid)

Without fire extinguisher

Without front passenger seat control

Without garage door opener

Without headlamp washer system

Without head-up display

Without integrated toll system

Without lane change assist

Without light control

Without preparation for rotating beacon/siren combination

Without preparation for two-way radio installation

Without preparation for VTS (vehicle tracking system)

Without rear spoiler

Without roll-up sunshade

Without roof insert (standard roof)

Without seat ventilation/massage seat

Without second battery

Without special body measures

Without trailer hitch

Without vehicle inlet

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Pirelli	Front	Left	Winter	Steel	215/60 R 16 95 H	2.0 mm
Pirelli	Front	Right	Winter	Steel	215/60 R 16 95 H	2.0 mm
Pirelli	Rear	Left	Winter	Steel	215/60 R 16 95 H	5.0 mm
Pirelli	Rear	Right	Winter	Steel	215/60 R 16 95 H	5.0 mm

Permitted: Yes

Roadworthy: No

UNMOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental			Summer	Aluminium	215/60 R 16 95 V	5.0 mm
Continental			Summer	Aluminium	215/60 R 16 95 V	5.0 mm
Continental			Summer	Aluminium	215/60 R 16 95 V	5.0 mm
Continental			Summer	Aluminium	215/60 R 16 95 V	5.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 02.2027

Compressor present: Yes

Jack present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Windscreen	Stone chip(s)	Replace
2	Tyres	Worn	Replace
3	Door FL	Dent(s)	Paintless dent repair
4	Roof pillar R	Dent(s)	Paintless dent repair
5	Bonnet	Dent(s)	Paintless dent repair
6	Inner door sill RR	Dent(s)	Paintless dent repair
7	Roof pillar L	Dent(s)	Paintless dent repair
8	Side wall RR	Residue	Polish
9	Door FL	Scratch(es)	Touch up

» Usage Damages

Nr	Location	Damage type	Repair type
1	Tailgate / Boot	Dent(s)	Acceptable

» Commercial devaluation

Accidental vehicle:	Yes
Known previous damages:	Yes
Previous damages detectable:	Yes
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

Nr	Location	Damage	Repair type	Repair cost
1	Other	Part of hull loss		€ 1,275.65
Total without VAT:				€ 1,275.65

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WVWZZZ3CZPE056105

VIN checked and matches documentation

Vehicle condition:

Average general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

No

Testdrive carried out:

No

Engine test carried out:

Yes

» **Remarks**

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4



Rear Right 3/4



Mileage



Tools




Sill outer L



Sill outer R




Chassis nr



Wheel FL



Wheel FR



Wheel RL



Wheel RR



Additional wheel 1



Additional wheel 2




Additional wheel 3



Additional wheel 4



Central console




Engine compartment



Documents



Interior arrangement



Registration Certificate



Tyres in vehicle



History Maintenance




Interior - front



Interior - rear



Tirefit expiration date



GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS

1 - Windscreen - Stone chip(s) - Replace





2 - Tyres - Worn - Replace

Comment



Achswise ersetzen



3 - Door FL - Dent(s) - Paintless dent repair



4 - Roof pillar R - Dent(s) - Paintless dent repair




5 - Bonnet - Dent(s) - Paintless dent repair




6 - Inner door sill RR - Dent(s) - Paintless dent repair




7 - Roof pillar L - Dent(s) - Paintless dent repair



8 - Side wall RR - Residue - Polish



9 - Door FL - Scratch(es) - Touch up



USAGE DAMAGES

1 - Tailgate / Boot - Dent(s) - Acceptable

