



Skoda Karoq:

Vinnumber:	TMBJF7NU1MC207606	Versionname:	
First Registrationdate:	15/06/2021	Fiscalpower:	
Expertise Mileage:	111251	Power Kw:	85
Bodytype:		Body colour:	Blue
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1122
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

	215/60/16/92 H			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/60 R 16 92 H
Tyre size FR				215/60 R 16 92 H
Tyre size RL				215/60 R 16 92 H
Tyre size RR				215/60 R 16 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	1664,50
-------------------	---------

Interior, Stain, Forfeit	125,00
--------------------------	--------



Bumper F, Scratch(es), Acceptable 0,00



Windscreen, Repaired, Acceptable 0,00




Wing RL, Dent(s) and scratch(es), Repair and paint (complete) 517,89



Door RL, Dent(s) and scratch(es), Repair and paint (complete) 534,95



Step L, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing L, Scratch(es), Acceptable 0,00



Wing FL, Chemical polution, Polish 0,00



Bumper trim R, Scratch(es), Smart repair

116,69



Rear window, Scratch(es), Acceptable

0,00



Wing FR, Chemical polution, Repair and paint (complete)

369,97



Door FR, Scratch(es), Acceptable

0,00



Door RR, Scratch(es), Acceptable

0,00



Wing RR, Dent(s), Acceptable

0,00

