


Vehicle data sheet

Vehicle details

Vin	VF1RJL009UC372574	Plate		Distance km	49908	Date immat	28/04/2023
Location	Pozzuoli (NA)					Appr. date	26/02/2026
Model	ARKANA			Color	Grigio grafite	Enamel type	Metall double







Documents

Registration certificate	V
Green card	X
Insurance certificate	X
Service booklet	V
Owner manual	V
Key code card	X
Second key	V
Master key	V

Vehicle info

Battery charged / compliant	V
Fuel level	1/2
Interior clean/acceptable	V
Interior material/colour	Leather / Dark
Exterior clean/acceptable	V
Plates compliant/readable	V

Accessories

Remote controls (Working)	V
Smoker kit	X
Radio/nav antenna	V
Audio unit (Working)	V
Navigator (Working)	V
Map support	PRELOADED
Floor mats	V

Equipment

Tool kit	V
Cylinder	V
Locking wheel bolt	V
First aid kit	V
Warning triangle	V
Hat rack	X
Luggage compartment mat	V

V - Elemento presente X - Elemento assente ? - Elemento presente ma non verificabile

Tires

Right front tire	Kumho	215/55/18	Summer	5.1 mm
Left front tire	Kumho	215/55/18	Summer	6 mm
Right rear tire	Kumho	215/55/18	Summer	4.7 mm
Left rear tire	Kumho	215/55/18	Summer	4.7 mm
Spare wheel	Ruotino			

Damage detail

Component	Left front wheel damaged	Side	
Component	Stacco riattacco disk wheel front left	Side	
Component	Right front wheel damaged	Side	
Component	Stacco riattacco disk wheel front right	Side	
Component	Left rear wheel damaged	Side	
Component	Stacco riattacco disk wheel rear left	Side	

Component	Right rear wheel damaged	Side	
Component	Stacco riattacco disk wheel rear right	Side	
Component	Tendalino engine compartment luggage	Side	
Component	Windscreen p lights auto manten lane 06 23	Side	
Component	Roof	Side	
Component	Roof moulding	Side	Left
Component	Bumper front part sup p assist parch	Side	
Component	Bumper dismantling	Side	
Component	Moulding lat bumper front p rs line	Side	Right
Component	Coating lower bumper front p rs line	Side	
Component	Moulding lat bumper front p rs line	Side	Left
Component	#PRM# Moulding arch wheel arch front	Side	Left
Component	#PRM# Grill fender front	Side	Left
Component	Shell rearview mirror ext.	Side	Left

Component	Door front	Side	Left
Component	Door rear	Side	Left
Component	Bumper rear central p rs line	Side	
Component	Bumper dismantling	Side	
Component	Coating lower bumper rear p rs line	Side	
Component	Shell rearview mirror ext.	Side	Right
Component	#PRM# Moulding arch wheel arch front	Side	Right

Descriptions legend

D.E: Defect of execution on previously repaired area

PRIMER: Component provided already pre trattato for the vernicia **PRM:** Normal wear