



BMW 2 Reeks Active Tourer (UKL): 2DQT277

Vinnumber:	WBA21BY0107M76204	Versionname:	218d Active Tourer (U06) 2.0d 136pk/cv 5p Aut.
First Registrationdate:	30/05/2023	Fiscalpower:	
Expertise Mileage:	104295	Power Kw:	100
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	NOT OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/65/16/95 W			
Summer tyres:	Fr.L.	Bridgestone: 2,5 mm	Fr.R.	Bridgestone: 2 mm
	Re.L.	Hankook: 3 mm	Re.R.	Hankook: 3 mm
Tyre profile depth FL				2.5
Tyre profile depth FR				2.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				205/65 R 16 95 W
Tyre size FR				205/65 R 16 95 W
Tyre size RL				205/65 R 16 95 W
Tyre size RR				205/65 R 16 95 W
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Check




Bumper F, Scratch(es), Spot repair



Bumper F, Scratch(es), Acceptable



Bonnet, Stone chip(s), Acceptable



Windscreen, Stone chip(s), Acceptable



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Scratch(es), Acceptable



Shutter / cover R, Broken, Repair/replace (lump sum)



Bumper R, Scratch(es), Acceptable





Door FR, Scratch(es), Acceptable



Bodywork, Paint measurement, Acceptable



Kenteken	2DQT277
Merk Model	BMW 218d Active Tourer (U06) 2.0d 136pk/cv 5p Aut.
Brandstofsoort	Diesel
Datum deel1	5/30/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
11/21/25	84,064	BMW/MINI service standaard omvang	Uitvoeren
11/21/25	84,064	remblokken achter	Vervangen
11/21/25	84,064	ruitenwisservloeistof	Bijvullen/-laden
9/15/25	72,503	batterij	Vervangen
9/15/25	72,503	BMW/MINI service standaard omvang	Uitvoeren
9/15/25	72,503	BMW/MINI service voertuig-check	Uitvoeren
9/15/25	72,503	ruitenwisserrubber achter	Vervangen
9/15/25	72,503	ruitenwisserrubber vooraan	Vervangen
9/15/25	72,503	service brandstoffilter	Uitvoeren
9/15/25	72,503	service luchtfilter	Uitvoeren
9/15/25	72,503	service microfilter	Uitvoeren
9/15/25	72,503	service motorolie	Uitvoeren
3/31/25	57,594	BMW/MINI service standaard omvang	Uitvoeren
3/31/25	57,594	remblokken vooraan	Vervangen
7/18/24	45,891	BMW/MINI service standaard omvang	Uitvoeren
7/18/24	45,891	service microfilter	Uitvoeren
7/18/24	45,891	service motorolie	Uitvoeren
11/16/23	21,185	controle niveaus	Uitvoeren