



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	BMW
Model / version:	X3
Vin:	WBA55BZ050N130264
Plate:	2BMB837
Mileage:	58486
First registration:	11/01/2022
Color:	Black Sapphi



ADDITIONAL INFORMATION








Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	1
Original key:	✓

PICTURES





VIN INFORMATION

depuis début de production (Facelift)
système de récupération
système d'accès confort

tuner DAB
filet de séparation coffre

sièges av Sport
dossiers ar réglables
appel d'urgence intelligent
Parking Assistant Plus
protection des piétons active
Driving Assistant

liquide de climatisation R1234YF
climatisation automatique à 2 zones
rétroviseurs ext/int jour/nuit automatique
et rabattables
système HiFi
pare-soleil à enrouleur aux vitres des
portes ar
sièges av chauffants
BMW Live Cockpit Pro
système d'alarme
1995 CC 110KW
245/50 R 19 .. W
Active Guard

pack de rangement
mesures CO2 étendues
contrôle gestuel

garnissage pavillon anthracite
garnissage sièges cuir "Vernasca"

vitrage ar avec protection solaire
dossiers réglables en largeur
rétroviseur int avec commande à distance
8 vitesses automatique
7,5 J x 19 Alu jet black
encarts intérieurs noir brillant avec
accents perle brillant chromés

toit ouvrant en verre panoramique
électrique
2 couches métallisée

indicateur de pression des pneus
Afrique du Sud (N)

spécifique Europe

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:		Fast charging cables:	

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer	Aluminium	?
Front right	5 mm			Summer	Aluminium	?
Rear left	5 mm			Summer	Aluminium	?
Rear right	5 mm			Summer	Aluminium	?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key	Missing
3	Spoiler bumper R	Scratch(es)
4	Outer door handle RR	Scratch(es)
5	Alloy rim FR	Scratch(es)

Total: 4

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

1 - Contact key - Missing



3



4 - Outer door handle RR - Scratch(es)



5 - Alloy rim FR - Scratch(es)



2 - Bodywork - Dent(s) and scratch(es) - Renta®

