



PEUGEOT 3008: GL-264-WP

Vinnumber:	VF3MCYHZUNS151615	Versionname:	PEUGEOT 3008 BlueHdi 130 S&S EAT8 Active Pack
First Registrationdate:	27/01/2023	Fiscalpower:	VP [5P] bva 8-130CH-7cv (SUV)
Expertise Mileage:	157402	Power Kw:	96
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Rear parking sensors	
Cruise Control		Seat cover lining	Lining Other
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Manual climate control		

Tyres

	215/65/17/103 V			
Summer tyres:	Fr.L.	Michelin: 60%	Fr.R.	Michelin: 60%
	Re.L.	Uniroyal: 30%	Re.R.	Uniroyal: 5%
Tyre profile depth FL				4.2
Tyre profile depth FR				4.2
Tyre profile depth RL				6.2
Tyre profile depth RR				7.8
Tyre size FL				215/65 R 17 103 V
Tyre size FR				215/65 R 17 103 V
Tyre size RL				215/65 R 17 103 V
Tyre size RR				215/65 R 17 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				261
Tyre make FR				261
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Jack	Yes
Interior, Stain, Cleaning	



Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Alloy rim RR, Scratch(es), Repair/replace (lump sum)



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Door lock FL, Strained, Replace



Door RL, Dent(s), Repair and paint (complete)



Bumper moulding F, Scratch(es), Replace



Bumper F, Scratch(es), Paint



Wing RR, Scratch(es), Paint



Door RR, Scratch(es), Paint



Door FR, Scratch(es), Paint



Boot lid covering R, Crack, Repair/replace (lump sum)



Internal boot lining R, Scratch(es), Replace



Internal boot lining L, Scratch(es), Replace



Historique Maintenance

Immatriculation: GL-264-WP Date de 1ère immatriculation: 27/01/2023

Modèle: Peugeot 3008 BlueHDi 130 S&S EAT8 Active Pack VP [5P] bva 8-130CH-7cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
23/03/2026	144.814	GARAGE CARBONNE	BALAIS ESSUIE GLACE AV
	0		REVISION
29/08/2025	116.841	GARAGE CARBONNE	DIAG
	0		CAPTEUR ABS ARD RPLT
	0		ESSAI
27/08/2025	116.512	GARAGE CARBONNE	DIVERS CLIM
	0		LIQUIDE DE FREIN
	0		REVISION ET CLIM ET AIR ET CARBURANT
	0		COURROIE ACCESSOIRES RPLT
16/05/2025	106.013	GARAGE CARBONNE	DIVERS CARROSSERIE
	0		GEOMETRIE CTRL
	0		CREMAILLE DE DIRECTION RPLT
	0		PLAQUETTES AV RPLT
19/03/2025	98.788	GARAGE CARBONNE	PLAQUETTES AR RPLT
	0		REVISION
18/11/2024	86.156	GARAGE CARBONNE	BALAIS ESSUIE GLACE AV AR
	0		REVISION
23/08/2024	73.342	GARAGE CARBONNE	ADBLUE
	0		REVISION
	0		DISQUES PLAQUETTES AV RPLT
26/03/2024	52.398	GARAGE CARBONNE	REVISION ET CLIM ET AIR ET CARBURANT
	0		PLAQUETTES AR RPLT
13/07/2023	20.053	GARAGE CARBONNE	REVISION