



Volkswagen CADDY 2.0 TDI 75pk L1H1 BMT Trendline Executive+, Feb-19, 162,468 km



Memo



VIN **WV1ZZZ2KZKX044677**

Initial registration **01-02-2019**

Initial Dutch Registration **01-02-2019**

European Type Approval **e1*2007/46*0217*29**

Mileage reading / hour counter reading **162,468 km** 

Mileage Status: **Logical (NAP)**

Automatic **No**

Fuel **Diesel**

Cylinders / Engine capacity **4 / 1968**

Weight **1376 kg**

Doors **4**

Power capacity **55 kW**

Emission code / Energy label **6**

Wheelbase **268**

Loading space

Load capacity **751**

RDW details

Battery capacity

Range

Battery health

Charging cables type

AC/DC

Battery purchase/rent **Unknown**

Taxation **VAT (Grey number plate)**

Colour **n/a**

Country of registration **The Netherlands**

Origin **Lease**

Accessories fitted to vehicles

 Apple Carpl./Android Car	 Cruise control	 Parking sensors rear
 Audio installation	 Electric windows front	 Sliding door right
 Automatic air conditioning ECC	 Lath to lath paneling / siding	 Power steering
 Bluetooth telephone connection	 Metallic paint	 Tow bar
 Central locking remote control	 Navigation	 Floor plate

Accessories fitted to vehicles (stated by offerer, conditionally)

- Achterdeuren met ruiten
- Achterruitverwarming
- Achterruitwisser
- Airco
- BAS
- Bestuurdersairbag
- Bluetooth telefoonvoorb.
- Boordcomputer
- Buitensp. elektr. + verw.
- ESD
- ESP
- Hill hold functie
- Hoofd airbag(s) v.
- Passagiersairbag
- Start/stop systeem
- Stoel best. hoogte verst.
- Stoel pass. hoogte verst.
- Vervolgbotsing preventie
- Volledig tussenschot
- Zij airbag(s) v.
- Zijschuifdeur rechts



Comments

No remarks

Vehicle state


MOT due date	04-02-2027	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	2	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location Owner	Wheel locks	Not present



Tyres

Rim size	15"	Type	Tread depth
Wheel	Brand		
Front wheel left	Hankook	All Season tyre	4 mm
Front wheel right	Hankook	All Season tyre	8 mm
Rear wheel left	Hankook	All Season tyre	6 mm
Rear wheel right	Hankook	All Season tyre	6 mm
Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection

Incident		Component	Observations
Unacceptable damage			
1		Interior	smoke odor
2	 	Bekl zitting v l	burn hole(s)
3	 	Dorpel l	distorted
			
4	 	Front door left	dent(s)
			
5	 	Bumper v bekleding	Gebroken
6	 	Bumper v r rooster	distorted
7	 	Schuifdeur r	distorted
			
8	 	Dorpel r	distorted
			
9	 	Front wing right	distorted
			
10		Front door right	scratch(es)

11



Rear door left

distorted

12



Koetswerk

Niet origineel

Comments

No remarks

Vendor