



RENAULT Megane: 7827-MNV

Vinnumber:	VF1RFB00172144462	Versionname:	S.T. Techno TCe 103 kW (140CV) EDC GPF familiar 103kW 5P automática
First Registrationdate:	6/03/2024	Fiscalpower:	
Expertise Mileage:	79329	Power Kw:	
Bodytype:	Break	Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:			
Fueltype:	Petrol		
Engine functioning	Yes		
Battery functioning	Yes		
Vehicle running	Yes		
Number of seats	5		
Number head rests	5		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	No		
Category	Passenger Car		
Registration Certificate Car (BE)	No		

Options

Number of keys total	2	Central consol F
Number keys remote	2	Luggage cover
GPS big screen color		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		Roof bar alu
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	Autom climate control	

Tyres

	205/50/17/93 Y			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				205/50 R 17 93 Y
Tyre size FR				205/50 R 17 93 Y
Tyre size RL				205/50 R 17 93 Y
Tyre size RR				205/50 R 17 93 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Door RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)




Wing RR, Scratch(es), Repair and paint (complete)



Alloy rim RR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check

