



BMW X1: [redacted]			
Vinnumber:	WBA71AC0603M14568	Versionname:	sDrive18dA (100 kW)
First Registrationdate:	12/05/2020	Fiscalpower:	
Expertise Mileage:	157384	Power Kw:	100
Bodytype:		Body colour	Black
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	2208
Fueltype:	Diesel		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options			
Number of keys total	2	Sun Roof electric	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar removable
Type of GPS	GPS base		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

225/55/17/97 W			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Bridgestone: 5 mm	Re.R.
Tyre profile depth FL	4.0		
Tyre profile depth FR	4.0		
Tyre profile depth RL	5.0		
Tyre profile depth RR	5.0		
Tyre size FL	225/55 R 17 97 W		
Tyre size FR	225/55 R 17 97 W		
Tyre size RL	225/55 R 17 97 W		
Tyre size RR	225/55 R 17 97 W		
Tyre type FL	Summer		
Tyre type FR	Summer		
Tyre type RL	Summer		
Tyre type RR	Summer		
Tyre make FL	256		
Tyre make FR	256		
Tyre make RL	255		
Tyre make RR	255		

Assistance equipment			
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	168,93
Floor covering FL, Burned, Smart repair	116,69



Seat cover FL, Worn, Acceptable		0,00
 		
Backrest cover FR, Scratch(es), Acceptable		0,00
  		
Bumper spoiler F, Scratch(es), Acceptable		0,00
 		
Bumper F, Scratch(es), Acceptable		0,00
   		
Door FL, Dent(s), Acceptable		0,00
 		
Mirror side repeater L, Crack, Replace		52,24
  		
Bumper R, Scratch(es), Acceptable		0,00
  		
Spare wheel, Missing, Check		0,00
		
Boot lid covering R, Scratch(es), Acceptable		0,00
 		
Bumper trim R, Scratch(es), Acceptable		0,00



Wing RR, Scratch(es), Acceptable

0,00



Step R, Scratch(es), Acceptable

0,00



Wing trim FR, Scratch(es), Acceptable

0,00



Roof, Chemical polution, Acceptable

0,00

