



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	AUDI
Model / version:	A4 AVANT
Vin:	WAUZZZF47PA011736
Plate:	
Mileage:	132955
First registration:	05/09/2022
Color:	NAVARRABLAUW





ADDITIONAL INFORMATION





Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES





VIN INFORMATION

Transmission séquentielle
Break
Matière : alliage
Diamètre arrière 17
Diamètre avant 17
Hauteur arrière 50
Largeur avant 225
Accoudoir central avant
Freins avant à disques
Rétroviseur droit à réglage électrique
Rétroviseur gauche jour/nuit automatique

7 rapports
Projecteurs à LED
Lettre repère (J)
Largeur avant 7,5
Diamètre arrière 17
Indice de vitesse avant H
Largeur arrière 225
Euro 6
Freins arrière à disques
Rétroviseur droit convexe
Rétroviseur droit jour/nuit automatique

5 portes
Feux arrière à LED
Diamètre avant 17
Largeur arrière 7,5
Hauteur avant 50
Indice de vitesse arrière H
Climatisation réfrigérant 1234YF
Métallisée vernissée
Rétroviseur gauche à réglage électrique
Rétroviseur gauche asphérique
Rétroviseurs rabattables électriques

Rétroviseur intérieur jour/nuit automatique	Siège avant gauche chauffant	Sièges avant chauffants
Garnitures cuir et simili-cuir	Volant cuir	Volant multifonction
Aide au stationnement avant	Aide au stationnement arrière	Caméra avant
Régulateur et limiteur de vitesse	Equipement Stop & Start	Affichage lecture des panneaux de signalisation
Carte mains libres	Ouverture du coffre électriquement	Appel de secours
Lunette arrière teintée foncée	Vitres portes arrière teintées foncées	Vitres de custode teintées foncées
Attelage avec boule amovible	Fixotoit chromé	Airbag passager
Airbag passager désactivable	Protection piéton	depuis 07.22
réservoir carburant 54 L	traitement des gaz d'échappement avec catalyseur SCR (AdBlue)	pack brillance
triangle de secours dans le couvercle ar	radio avec récepteur numérique	dossiers ar séparés
alternateur renforcé 130/200 A	1968 cc (2,0 L) 100 KW	roues av motrices (traction)
transmission hybride M-HEV	garniture bas de caisse	grille de calandre sans plaque immat
Advanced		

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Summer		?
Front right	4 mm			Summer		?
Rear left	4 mm			Summer		?
Rear right	4 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Bumper R	Scratch(es)
3	Tailgate / Boot	Scratch(es)
4	Boot lid covering R	Scratch(es)
5	Door RR	Dent(s)
6	Alloy rim FR	Scratch(es)
7	Wing FR	Dent(s) and scratch(es)

Total: 6




ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Damaged	✓	✗	✗

Total: 1

DAMAGES DETAILS


2 - Bumper R - Scratch(es)



3 - Tailgate / Boot - Scratch(es)



4 - Boot lid covering R - Scratch(es)



5 - Door RR - Dent(s)





6 - Alloy rim FR - Scratch(es)






7 - Wing FR - Dent(s) and scratch(es)



1 - Bodywork - Damaged - Renta®





SIGNATURE

Expert
30/07/2026 09:03
