

» Overview

Order number: 1002504253
Order completed: 19.06.2026 12:36
Report number: 10837605
VIN: WAUZZZFY5R2079985



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Audi
Model:	Q5
Manufacturers and type code:	0588 / BQW
Date of first registration:	27.06.2024
Mileage:	34,883 km
Proof of mileage:	ReadOff
Exterior colour:	Brillantschwarz
Roof colour:	Brillantschwarz
Propulsion:	4 Wheel-drive
Fuel:	Hybrid Diesel
Engine size (cc):	2,000 ccm
Performance:	150 kW (205 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	4
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 7-speed
Upholstery type:	Lining fabrics
Interior colour:	schwarz-schwarz/schwarz-schwarz/schwarz/titangrau
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	06.2027
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	Both
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	25,200 KM

4-cyl. turbo diesel engine 2.0 l/150 kW (4V) TDI, common rail
 base engine is T6F/T98/T48/T4T/T1T/T1H

4-cylinder diesel engine 2.0 l unit 05L.A

Accent surfaces, Matt Black

AdBlue tank

Airbags, front; front passenger airbag can be deactivated

All-season tires 235/60 R18 103V

Audi AG

Audi connect emergency call & service with Audi connect
 remote & control

Audi connect navigation & infotainment

Audi drive select

Audi new car tire warranty

Audi phone box

Audi pre sense city

Audi sound system

Audi virtual cockpit plus

Automatic air conditioning

Axial and vertical adjustable steering column

Basic

Basic equipment variant

Battery 380 A (68 Ah)

Belt-driven integrated starter alternator 12 V, 130 - 200 A

Beverage holders

Black decorative trims

Box

Business package

Camera-based traffic sign recognition

Carrier frequency 433.92 MHz-434.42 Mhz

Category 0

Comfort center armrest, front

Complete protective cover (made-to-measure system)

Control code 8

Control of series production

Country group A

Cruise control with speed limiter

Data module, Europe

Daytime running lights

Diesel engine

Digital Audio Broadcasting

Disc brakes in rear, 17-inch (ECE)

Disk brakes, front, 17-inch (ECE)

Door sill trims with aluminum inlays, front

Driving on the right

Electric auxiliary air heater

Electromechanical power steering

Electronic immobilizer

Emission standard, WLTP3 M1, N1-I/EU6EA

Equipment options subset for Germany

Extended pedestrian protection

Exterior mirror housings in body color

Exterior mirrors, electrically adjustable, heated and folding,
 automatically dimming on both sides

Filler neck module 1 without insert

First-aid kit with warning triangle and high-visibility vests

Floor mats, front and rear

Front seats, manually adjustable

Fuel system for diesel engine

Fuel tank

Gearshift/selector lever handle

Head restraints, front

Headlining in cloth in specific color

High beam assistant

Hold assist

Increase in initial standard fuel filling

Inlays, Micrometallic, Silver

Installation parts for four-cylinder engine

Instrument cluster, km/h speedometer

Interior lighting

Interior mirror, automatically dimming, frameless

ISOFIX child seat mounting and top tether for the outer rear
 seats

Labels in English and German

Lane departure warning

Leather steering wheel, 3-spoke with multifunction plus

LED headlights

LED rear lights

Left exterior mirror, aspherical

Left-hand drive

Loading floor

Loading sill protector, plastic

LTE support for Audi phone box

Luggage compartment cover

Luggage compartment lid, electrically opening and closing

Luggage compartment mat

Manual child safety lock

Manual in German	Standard pedal cluster
Manual sunshade for the rear door windows	Standard seats, front
Mild hybrid	Standard suspension
MMI navigation plus with MMI touch	Standard suspension
No self-collection	Standard wheel bolts
No special edition	Standard-production quality
No special purpose vehicle, standard equipment	Start-stop system
Non-smoker version	Sun protection glass, tinted
Not hot country	Sun visors, front
Not leather-covered	SWIN management
Omission of model name and output/technology logo	Synonym cloth
Operating permit, alteration	tiptronic
Parking system plus	Tire pressure loss indicator
Part set without country-specific prescriptive standard	Tire repair kit
Partition net	Tires without specification of tire brand
Passenger car design	Trailer hitch
Preparation for functions on demand	Transit coating (type 2)
Production wheels	Two-tone horn
Q5	Type approval country Germany
quattro	Vehicle class differentiation -FY0/FYF-
quattro with ultra technology	Vehicle tool kit (without vehicle jack)
Rear and side windows with heat-insulating glazing	Vehicles with special upgrade measures
Rear spoiler	Weight category front axle weight range 5
Rear trim panel (ECE)	Weight range 7 installation control only, no requirement forecast
Refrigerant R1234yf	Wheels, 5-twin-spoke dynamic, 8.0J x 18 235/60 R18 tires
Regional code " ECE " for radio	Windshield with heat-reflecting glass and acoustic glass
Reinforced bumpers	With multifunction camera
Remote control key, without Safelock	With special labels safety certificates for Germany
Reversing camera	Without acoustic vehicle alerting system
Right exterior mirror, aspherical	Without additional front underbody guard
Roof rails in Black	Without additional tires
S tronic (for all-wheel drive)	Without additional warning lights
Seat belt reminder	Without alcohol interlock
Seat heating, front	Without auxiliary heater/parking heater
Service indicator 30 000 km or 2 years (variable)	Without Car2X
Side airbags, front and head airbag system	Without charging cable for public charging (AC), mode 3
Smartphone interface	Without child seat anchorage in front (ISOFIX)
Special identification label (EU)	Without danger alarm system
Split-folding rear seat backrest	Without decorative films/emblems
Standard	Without electric motor (hybrid)
Standard climatic zones	Without e-tron charging system compact (AC), without mains cable for domestic connector
Standard electric	Without extended safety system
Standard manufacturing sequence	

Without fire extinguisher
Without front license plate carrier
Without garage door opener
Without headlamp washer system
Without head-up display
Without ignition/starter switch locking system, without steering lock
Without integrated toll system
Without lane change assist
Without locking and starting systems
Without lumbar support in seat backrests
Without mains cable for industrial connector for the e-tron charging system
Without preconditioning
Without preparation for VTS (vehicle tracking system)
Without roof insert (standard roof)
Without seat ventilation/massage seat
Without special body measures
Without step
Without Storage package
Without vehicle inlet
Without wall mount

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Michelin	Front	Left	All season	Aluminium	235/60 R 18 103 V	5.0 mm
Michelin	Front	Right	All season	Aluminium	235/60 R 18 103 V	5.0 mm
Michelin	Rear	Left	All season	Aluminium	235/60 R 18 103 V	5.0 mm
Michelin	Rear	Right	All season	Aluminium	235/60 R 18 103 V	5.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 02.2029

Compressor present: Yes

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Wing FR	Scratch(es)	Spot repair
2	Door FL	Dent(s)	Paintless dent repair

» Usage Damages

Nr	Location	Damage type	Repair type
1	Bumper F	Stone chip(s)	Acceptable
2	Bonnet	Stone chip(s)	Acceptable
3	Bumper R	Scratch(es)	Acceptable
4	Tailgate / Boot	Abrasion	Acceptable

» Commercial devaluation

Known previous damages:	No
Previous damages detectable:	No
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment**Details of the assignment and the scope of the assessment:**

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WAUZZZFY5R2079985

VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

No

Engine test carried out:

Yes

» Remarks

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures



Front Left 3/4



Front Right 3/4



Rear Left 3/4




Rear Right 3/4




Mileage



Tools



Sill outer L



Sill outer R



Chassis nr




Wheel FL



Wheel FR



Wheel RL



Wheel RR



Central console



Engine compartment



Documents




Interior arrangement



Registration Certificate



Charging cable (normal)



Towbar



History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



Underbody scan



GPS/Radio


» Devaluation Damages

DEVALUATION FACTORS

1 - Wing FR - Scratch(es) - Spot repair



2 - Door FL - Dent(s) - Paintless dent repair



USAGE DAMAGES


1 - Bumper F - Stone chip(s) - Acceptable



2 - Bonnet - Stone chip(s) - Acceptable



3 - Bumper R - Scratch(es) - Acceptable



4 - Tailgate / Boot - Abrasion - Acceptable

Comment

Heckklappe quitscht beim Oeffnen

