VEHICLE REPORT

IT · 04/11/2026
2026-11-04 17:07

VIN: Targa: Merchant:

VEHICLE DETAILS

Targa		First Registration	**2024-04-29**
Marca	N/A	Mileage	N/A
Modello e Allestimento		Keys	N/A
VIN		Owners	**2**
Merchant		Seats	**5**
Branch		Previous Use	**AUTOVEICOLO PROPRIO AUTOVETTURA PER TRASPORTO DI PERSONE**
KW	**350**	VAT	N/A
CC	**0**	Country	**IT**
Fuel	**BENZ-ELETTR**	Euro	**EURO6E**
GPL	**Non presente**	Cambio	**Non presente**
Gancio	N/A		

CAR PHOTOS (81)


Front


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Upload


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Rear fender left


Underbody view


Rear fender left


Left side rear


Front left


Interior rear


Center console and dashboard


Engine compartment


Interior front


Interior front


Navigation on.


Interior front


Front door left


Interior front.


Interior front


Speedometer with started engine


Navigation on


Interior front


Center console and dashboard


Interior rear


Interior rear


Interior rear


Interior front


Interior front


Interior front


Interior front


Interior front.


Interior front


Interior front.


Front door left


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Additional photos (optional)


Roof


Left side front


Front door left


Front door left


Rear fender right.


Left side front


Left side rear


Left side front


Left side front


Front left


Front left


Front left


Left side front


Left side front


Rear


Interior rear


Trunk


Trunk


Trunk


Rear


Rear


Front left



Front fender left

Left side front

Front left

Front.

Engine compartment

Hood

CARFAX Vehicle History Report

MERCEDES AMG GLC 63S E PERFORMANCE

Vehicle reference:
W1NKM8AB9RF111581

Body type:
Estate

Engine size:
1991 cm³

Total system power:
350 kW / 476 hp

Combustion engine power:
350 kW / 476 hp

Gearbox type:
Automatic

Hybrid vehicle:
Electric, Petrol

Quick check

Damage
This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

Import
Not a private import

Legend


- No issues reported or indicated
- Valuable Information
- Requires attention
- Data unavailable

Damage overview

02/2025

Affected area (2):

Location reference, does not indicate the extent of the damage.



Right

Right rear

Reported in

Italy

Damage type/cause

Not available

Damage severity:

Minor

Cosmetic damage only, including small dents or scratches that may need touch-ups. Does not affect vehicle operation or safety.

Damage Glossary

Damage

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

CARFAX tips



Keep in mind: while our data shows no further damage, additional events may have occurred. CARFAX only reflects information that's been reported to us.

It's still important to take a close look at the vehicle during your test-drive. Small details can sometimes hint at past repairs. Keep an eye out for paint inconsistencies or uneven panels.

Recommended maintenance

Default schedule
Provided by CARFAX Europe

Vehicle age
2 years, 6 months

Maintenance due so far

These service tasks are expected based on the vehicle age. Verify if they were completed.

Before buying, ask the seller:
- Are service records available?
- Were the following services performed?

Engine oil and oil filter **due 2 times**
Change every year

Brake fluid **due 1 time**
Change every 2 years

Costly upcoming service tasks

Before buying, confirm whether:
- Any of the upcoming maintenance tasks are already completed.
- You've accounted for related costs in your future budget.

Brake discs and pads
Inspect yearly, replace as needed

Tires
Inspect yearly, replace as needed

CARFAX tips



Keeping up with scheduled servicing is a strong indicator that the vehicle has been well cared for and is in good overall condition.

Owners BETA



Owner(s) in Italy

Purchase year:
2024

Damage reported on:
02/2025

Technical details

Engine and performance

Hybrid vehicle
Electric, Petrol

Combustion engine power
350 kW / 476 hp

Electric engine power
Not available

Total system power
350 kW / 476 hp

Environment and consumption

EU emission standard
Euro 6

Weight

Curb weight
2 310 kg

Max payload
575 kg

Gross vehicle weight
2 885 kg

Dimensions

Length
4 751 mm

Width
1 938 mm

Wheelbase
2 888 mm

Other information

European vehicle category
M1

EU standard code
e1*2018/858*00186*04

Number of doors
5

Number of seats
5

History information

Date	Mileage	Event
2024-04-29		**Registered in Italy**
02/2025		**Damage reported in Italy**

For this Vehicle History Report, we searched over 40 billion records from more than 30 European countries, the USA, and Canada.

CARFAX Glossary

Number of records

A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

Quick check

A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

Severity scale - Minor

Generally, minor damage is cosmetic (including dents or scratches), may only require reconditioning, and typically does not compromise a vehicle's operation and/or safety.

Severity scale - Moderate

Moderate damage may affect multiple components of the vehicle and may impair the vehicle's operation and/or safety.

Severity scale - Severe

Severe damage usually affects multiple components of the vehicle and is likely to compromise the vehicle's operation and/or safety.

Vehicle reference

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.

How to use this report



This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time. Read more in our Terms and conditions.