



Volkswagen ID4: 2BVN697

Vinnnumber:	WVGZZZE2ZMP027458	Versionname:	
First Registrationdate:	9/08/2021	Fiscalpower:	
Expertise Mileage:	87372	Power Kw:	
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:	Back		
Fueltype:	Electric		
Maintenance:	OK		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Seats electric F L:	
Number keys remote:	2	Seats electric F R:	
Windows electric F:		Panoramic roof:	
Windows electric R:		Central consol F:	
Board Computer:		Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Steering wheel leather:		Roof bar alu:	
Seats F heated:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather and alcantara		
Type of climate control:	Autom climate control		
Type of radio:	Multimedia		
Type of GPS storage:	HD		

Tyres

235/45/21/101 T				
Winter tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm
Tyre profile depth FL				7.0
Tyre profile depth FR				7.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				235/45 R 21 101 T
Tyre size FR				235/45 R 21 101 T
Tyre size RL				255/40 R 21 102 T
Tyre size RR				255/40 R 21 102 T
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				256
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Instrument panel, complete, Not functioning (well), Check



Bonnet, Hail damage, Paintless dent repair (hail)



Bumper moulding F, Deformed / Strained, Replace



Wing RL, Hail damage, Paintless dent repair (hail)



Alloy rim RL polished, Scratch(es), Acceptable



Door RL, Dent(s), Acceptable



Roof pillar L, Hail damage, Paintless dent repair (hail)



Alloy rim FL polished, Scratch(es), Repair and paint (complete)





Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Rear spoiler, Hail damage, Paintless dent repair (hail)



Rear light R, Broken, Replace



Bumper R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable



Roof pillar R, Hail damage, Paintless dent repair (hail)



Door RR, Dent(s), Paintless dent repair



Door trim RR, Dent(s), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Acceptable

