

INSPECTION REPORT

End of contract

GENERAL INFO

File	315367
License plate	2CKY674
Vehicle identification number	TMBJG8NXXPY011670
Dossier	2021 272 127
Make	Skoda Oct.Com.2.0TDI 85kW Clev
Mileage	175463
First registration	30/08/2022
client availability date	15/06/2026
inspectionDate	29/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
15	Bumper Front // Replace & Painting	N
40	Windshield // Repair	Y
72	Side View Mirror Left // Painting	Y
80	Door Front Left // Smart Repair Small	Y
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	Y
191	Door Rear Right // Smart Repair Medium	N
216	Door Front Right // Polish	Y
222	Side View Mirror Right // Painting	N
321	Wheel Alloy Rear Left // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
544	Interior / Floor Covering / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures






Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front // Replace & Painting-cracked




Interior Cleaning // Small-stain



Windshield // Repair-stone chipping



Interior / Floor Covering / Replace-hole



Wing Rear Right // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch





Rear Bonnet // Polish-scratch



Bumper Rear // Painting-scratch



Light / Rear Right / Replace-scratch



Light / Rear left / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Door Rear Left // Polish-scratch





Door Front Left // Smart Repair Small-scratch



Side View Mirror Left // Painting-scratch



Door Front Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Trunk Compartment / Side Cover Left / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch






Front Right Door Interior Coating // Replace Completely-scratch



Door Rear Right // Smart Repair Medium-dent





See External Expertise-dent