BMW

BMW X5 (G05)(08.2018->) XDRIVE 45 E HYBRIDE 290 KW (MOTEUR 3,0 LITRE(S) - 210 KW) 5 PORTES

VIN: WBATA610909L51915



Description

Registration number 2CCF168	**Registration date** 01/06/2022	**Odometer** 74704 km
Color BLACK SAPPHIRE METALLIC	**Year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 2998	**Gearbox type** Automatic	**Engine type** Plug-in Hybrid
Fuel Type Petrol	**Number of gears** 8	**Max power** 290 KW

Vehicle Equipments

Standard

Service system: Remote 3D View	3. brake light LED	center armrest rear
center armrest front	airbag driver side/passenger side	sidebag front
alarm system	head rests rear	driver assistance system: brake assistant (Audi pre sense front)
BMW Live cockpit Professional	hands-free system Bluetooth	audio navigation system Professional
automatic transmission - with Steptronic (8-speed)	body: 5-door	automatic air-conditioning system with automatic recirculation control
steering column (steering wheel) electrically adjustable	dynamic stability control (DSC)	tire pressure control system
radio reception digital (DAB)	power steering Servotronic	theft protection for wheels (rim locks)
rear seat backrest split/folding (40:20:40)	dynamic brake light	light and rain sensor
anti-theft warning system + interior scanning / towing protection + back-up alert horn	wheelbase 2975 mm	Entretien: Véhicule avec Intervalle de vidange d'huile 30000 Km / 24 mois
seat equipment: 5-seater	interior equipment interior trim strips aluminium Mesheffect	rear lights LED
Interior filter: activated-carbon filter (odor filter)	gasoline particulate filter (GPF)	refrigerant R 1234 YF
parking brake electromechanical	windshield washer jets heated	liftgate two-piece
light alloy rims 9x19 (V-spoke 734, Reflex silber)	map lights in rear seat area	map light front
vehicle speed limiter	window lifter electric	Type of drive: all-wheel drive
Type of drive: xDrive (all-wheel drive)	model variant CO2 scope (code 1CB)	Moteur 3,0 litre(s) - 210 kW Hybride (B58)
electric motor 83 kW (hybrid drive)	multiple function for steering wheel	low emissions according to emission standard Euro 6 RDE
Equipment package: Connected Professional	Equipment package: Connected Teaser	Service system: Apple CarPlay information (preparation)
Service system: Remote Services	infotainment system: Cadillac User Experience (CUE) with touchscreen	Service system: Real Time Traffic Information (RTTI)
non-smoking package	Parkpilot system front and rear	Pneus 255/55 R18 ...W
USB port	power outlet (12V outlet) 3-fold	front fog lights LED

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

scuff rails with lettering BMW (illuminated)
acoustic pedestrian protection (external sound)
underride protection
air spring with ride-level control
headlight leveling control (automatic)
cruise control with brake function
exterior mirror electrically folding, all mirror with automatic dimming
exterior mirror electrically adjustable and heated
seats front electrically adjustable (left with Memory)
sports seats front
beverage holder front and rear
Isofix mounts for child seat
floor mats velours
head airbag system rear
head airbag system front
antilock braking system (ABS)
driver assistance system: Active Guard plus (lane assist, front-end collission warning)
driver assistance system: reversing assistant
driver assistance system: alertness assistant
driver assistance system: driving-experience switch
personalization system (Personal Profile)
pedestrian protection system
Service system: intelligent emergency call incl. TeleServices
Service system: ConnectedDrive Services
Service system: eDrive Services
start/stop system
cargo space partition (net)
hands-free system Bluetooth with extended smartphone bonding
tire puncture indicator
Steering AV European market (EU specific)
central locking system with remote control
central locking system with theft protection and crash sensor
heat protection glazing tinted
steering wheel (sport/leather)
exhaust system (left/right) with chrome trim covers
ambient lighting
daytime running lights LED

Optional

head-up display
BMW Display-Key
active hood
trailer coupling (pivoting ball head)
roof liner anthracite (BMW Individual)
Easy-Parking package
surround-camera system (Surround View)
metallic paintwork
headlight LED with adaptive light distribution
driver assistance system: high-beam assistant
active curve lighting
cruise control, active with Stop&Go function
driver assistance system: speed limit display
seat covers/upholstery: leather Vernasca perforated
seat heating front
driver assistance system: active lane-keeping assistant
driver assistance system: wrong-way-driving alert
driver assistance system: BMW gesture control
driver assistance system: Driving Assistant Professional
driver assistance system: intersection assistant
driver assistance system: intersection assistant
driver assistance system: collision avoidance assistant
système de récupération des gaz d'échappement (Blow-by-Heater)
sun protection glazing (rear darkened)
glazing acoustic glass

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	13/10/2026	14/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Rim / Front Right Rim/Tyre diameter : 19 "	Scratched	Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.





002	Door / Back Right	Improper Repair	Repair




003	Door / Back Right [1]	Improper Repair	Repair







004	Hook /Hicth ball / -	Defective	Check



005	C-pillar trim / Back Left	Scratched	Replace

006	C-pillar trim / Back Right	Scratched	Replace




007	Exhaust tip / Back Left	Defective	Warranty




All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

008	Tailgate / Boot door / -	Dent	Acceptable




009	Wing / Back Left	Dent	Acceptable



010	Door / Back Left [2]	Scratched	Acceptable




011	Rim / Front Left Rim/Tyre diameter : 19 "	Scratched	Repair




012	Wing / Front Right	Dent	Repair






013	Door sill / Back Right [3]	Scratched	Acceptable





014	Door / Front Right	Chip	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

015	Bumper / Front [4] Painted : Yes	Improper Repair	Repair




[1] Sur réserve pour échanger => porte en aluminium

[2] Polissage

[3] Polissage

[4] Enfoncement et décollement du vernis!

Loose Items

- [x] Slow charging cable (Type 2, Mode 2)
- [x] Quick charging cable (Type 2, Mode 3)
- [x] Load cover
- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Hook /Hicth ball
- [x] Spare Key
- [x] User manual
- [x] Document holder

Main set of tyres

Front Left	CONTINENTAL	265/50/19 Summer	7 mm
Front Right	CONTINENTAL	265/50/19 Summer	7 mm
Back Left	PIRELLI	265/50/19 Summer	6 mm
Back Right	PIRELLI	265/50/19 Summer	6 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left



Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right



Odometer



Navigation


Cable




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Door / Back Right / Improper Repair



Door / Back Right / Improper Repair



Door / Back Right / Improper Repair




Door / Back Right / Improper Repair



Door / Back Right / Improper Repair



Door / Back Right / Improper Repair



Hook /Hicth ball / - / Defective



C-pillar trim / Back Left / Scratched



C-pillar trim / Back Left / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



C-pillar trim / Back Right / Scratched



C-pillar trim / Back Right / Scratched



Exhaust tip / Back Left / Defective



Exhaust tip / Back Left / Defective



Tailgate / Boot door / - / Dent



Tailgate / Boot door / - / Dent



Wing / Back Left / Dent



Door / Back Left / Scratched



Door / Back Left / Scratched



Rim / Front Left / Scratched



Rim / Front Left / Scratched



Wing / Front Right / Dent



Wing / Front Right / Dent



Wing / Front Right / Dent



Door sill / Back Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Front Right / Chip



Door / Front Right / Chip




Bumper / Front / Improper Repair



Bumper / Front / Improper Repair



Bumper / Front / Improper Repair



Bumper / Front / Improper Repair



Bumper / Front / Improper Repair

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.