MACADAM







BMW X1 sDrive18i: 2CQT877

Vinnumber:	**WBA31AA0X03L45255**	Versionname:	
First Registrationdate:	**18/10/2019**	Fiscalpower:	
Expertise Mileage:	**125328**	Power Kw:	
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**MAN 6 VIT**		
Transmission:			
Fueltype:	**Petrol**		
Maintenance	**OK**		
Maintenance	**11000 km - 02/2028**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		
Registration Certificate Home (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**No Tow bar**
Type of headlighting	**Headlighting Halogen**		
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**225/55/17/97 W**			
	Fr.L.	**Continental: 5 mm**	Fr.R.	**Continental: 5 mm**
	Re.L.	**Continental: 5 mm**	Re.R.	**Continental: 5 mm**

Tyre profile depth FL	**5.0**
Tyre profile depth FR	**5.0**
Tyre profile depth RL	**5.0**
Tyre profile depth RR	**5.0**
Tyre size FL	**225/55 R 17 97 W**
Tyre size FR	**225/55 R 17 97 W**
Tyre size RL	**225/55 R 17 97 W**
Tyre size RR	**225/55 R 17 97 W**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**256**
Tyre make FR	**256**
Tyre make RL	**256**
Tyre make RR	**256**

Assistance equipment

Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**0**

Ignition key, Not functioning (well), Acceptable



Engine insulation, Tear, Replace







Bumper F, Scratch(es), Acceptable






Door FL, Dent(s), Acceptable

Bumper trim R, Scratch(es), Acceptable




Tyre repair kit, Missing, Check



Bumper R, Scratch(es), Acceptable




Wing FR, Scratch(es), Acceptable




Bodywork, Paint measurement, Acceptable

