

2-DPJ-778

2-DPJ-778 · ST-line 125pk 92kw mHEV M6 5d · 15 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DPJ-778	Fuel Type	Hybrid Gasoline
Manufacturer	FORD	VIN	WF0NXXGCHNPL84049
Model	Focus	Cylinder Capacity	999 ^{cm³}
Model Versions	ST-line 125pk 92kw mHEV M6 5d	Transmission Type	Handmatig geschakelde transmissie
Body Type	5 door hatchback	First Admission	15-05-2023
Color	Blue	Odometer	100.710 ^{Km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2023	Interior	Black
KW	92	Number Headrests	5

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Steeringwheel - Heated

Windscreen - Heated

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs

Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Left	6 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Front Right	2 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Rear Right	6 ^{mm}	Goodyear	215 ^{mm}	50 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part
Fender - Rear Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Reardoor - Left

Damage Type
Small scratch(es)

Repair Type
Polish

Acceptable
No



Damage Part
Frontdoor - Left

Damage Type
Small dent(s)

Repair Type
Restyle / Touch-up

Acceptable
No



Damage Part
Alloy - Left Front

Damage Type
Damaged

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Hood

Damage Type
Stonechipping

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Alloy - Right Front

Damage Type
Damaged

Repair Type
Rim repair

Acceptable
No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor - Right	Small scratch(es)	Deurgreep	Touch-up / Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Small scratch(es)	Touch-up / Polish	No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Rear	Missing	Trekoogkapje	Replace	No





Damage Part
Bumper - Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Tailgate

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Skirt - Right

Damage Type
small dents / small scratches

Repair Type
Restyle / Touch-up

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No