DEKRA

DEKRA Automotive Solutions


# Appraisal Report

## Vehicle details

| | | | | | |
|---|---|---|---|---|---|
| VIN | VR3FPHNS3 RY569422 | Registration date | 04/07/2024 | Exterior Color | Unknown |
| Brand | PEUGEOT | Licence Plate | PA-AR 339 | Odometer | 27 495 km |
| Model | 308 PureTech 130 EAT8 Allure | | | | |

## Inspection Details

| | | | | | |
|---|---|---|---|---|---|
| Arrival Date | 23/07/2026 | Inspection ID | 7079291 | Inspection date | 28/07/2026 |
| Assign Date | 23/07/2026 | Fleet owner | Leasys Privat Leasing | Inspection loc. | Leasys AKB Kitzingen |



## Generic equipment

## Removable element

| | |
|---|---|
| Spare wheel kit | ✓ |
| Rear parcel shelf | ✓ |
| Hook /Hicth ball | ✓ |

## Technical Document

| | |
|---|---|
| User manual | ✓ |
| Warranty booklet | ✓ |
| Log books | ✓ |
| Spare key | ✓ |
| Key | ✓ |
| Remote key | ✓ |
| Service | ✓ |

## Tyres

Michelin 225/45/17 V Summer 5.0 mm

Michelin 225/45/17 V Summer 5.0 mm

Michelin 225/45/17 V Summer 5.0 mm

Michelin 225/45/17 V Summer 5.0 mm

## Exception / Damage

**1**

| | | | | | |
|---|---|---|---|---|---|
| Part | Bumper | Repair Time | - | Part Cost | - |
| Position | Front | Repair Cost | - | Gross Cost | - |
| Damages | Worn out | Paint Time | - | Depreciation % | 15.00% |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | For info | Flat Rate | - | **Net Cost** | - |

DEKRA

DEKRA Automotive Solutions

# Appraisal Report

**2**



| | | | | | |
|---|---|---|---|---|---|
| Part | Bonnet | Repair Time | - | Part Cost | - |
| Position | - | Repair Cost | - | Gross Cost | - |
| Damages | Worn out | Paint Time | - | Depreciation % | 15.00% |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | For info | Flat Rate | - | **Net Cost** | - |

**3**



| | | | | | |
|---|---|---|---|---|---|
| Part | Windscreen | Repair Time | - | Part Cost | - |
| Position | Front | Repair Cost | - | Gross Cost | - |
| Damages | Worn out | Paint Time | - | Depreciation % | - |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | For info | Flat Rate | - | **Net Cost** | - |

## Summary Inspection

| | | | | | |
|---|---|---|---|---|---|
| Gross Price | 0.00€ | Depreciation | - | Net Price | 0.00€ |

## Labor cost summary

| | Hourly Rate | Time | Gross Price | Depreciation % | Depreciation | Net Price |
|---|---|---|---|---|---|---|
| Bodywork | 0.00€ | 0.00 | 0.00€ | - | - | 0.00€ |
| Paintwork | 0.00€ | 0.00 | 0.00€ | - | - | 0.00€ |
| Paint preparation | 0.00€ | 0.00 | 0.00€ | - | - | 0.00€ |

## Miscellaneous

| | Gross Price | Depreciation % | Depreciation | Net Price |
|---|---|---|---|---|
| Small parts / disposal charge | 0.00€ | - | - | 0.00€ |
| Part Cost | 0.00€ | - | - | 0.00€ |
| Flat Rate | 0.00€ | - | - | 0.00€ |