



## VOLKSWAGEN TOURAN: [REDACTED]

Vinnumber:	<b>WVGZZZ1TZW019686</b>	Versionname:	<b>1.5 TSi Highline DSG</b>
First Registrationdate:	<b>18/12/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>119353</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:		Parking lot:	<b>1532</b>
Fueltype:	<b>Petrol</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>Yes</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Number of keys total	<b>2</b>	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting LED</b>	Type of Tow bar	<b>Tow bar collapsible</b>
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining semi-Alcantara</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

## Tyres

<b>205/60/16/92 H</b>				
Winter tyres:	Fr.L.	<b>Pirelli: 5 mm</b>	Fr.R.	<b>Pirelli: 5 mm</b>
	Re.L.	<b>Vredestein: 5 mm</b>	Re.R.	<b>Vredestein: 5 mm</b>
Tyre profile depth FL				<b>5.0</b>
Tyre profile depth FR				<b>5.0</b>
Tyre profile depth RL				<b>5.0</b>
Tyre profile depth RR				<b>5.0</b>
Tyre size FL				<b>205/60 R 16 92 H</b>
Tyre size FR				<b>205/60 R 16 92 H</b>
Tyre size RL				<b>205/60 R 16 92 H</b>
Tyre size RR				<b>205/60 R 16 92 H</b>
Tyre type FL				<b>Winter</b>
Tyre type FR				<b>Winter</b>
Tyre type RL				<b>Winter</b>
Tyre type RR				<b>Winter</b>
Tyre make FL				<b>264</b>
Tyre make FR				<b>264</b>
Tyre make RL				<b>2480</b>
Tyre make RR				<b>2480</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Number of charging cables (normal)	<b>0</b>		
Number of charging cables (rapid charge)	<b>0</b>		

Total cost ex VAT	<b>442,43</b>
-------------------	---------------

Door panel RL, Scratch(es), Smart repair	<b>116,69</b>
--	---------------



Seat cover FR, Stain, Cleaning 29,16



Windscreen, Repaired, Acceptable 0,00



Door FL, Dent(s), Repair and paint (complete) 0,00



Bumper R, Scratch(es), Repair and paint (complete) 296,58



Rear window, Scratch(es), Acceptable 0,00




Tailgate / Boot, Dent(s), Acceptable 0,00



Alloy rim FR, Scratch(es), Acceptable 0,00



Outside rear-view mirror housing R, Scratch(es), Acceptable 0,00



Wing RR, Scratch(es), Acceptable 0,00



Door RR, Dent(s), Acceptable 0,00

