


2-EDQ-066


2-EDQ-066 · Acenta L1H1 DIG-T 130 MT · 22 June 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EDQ-066	Fuel Type	Gasoline
Manufacturer	NISSAN	VIN	VNVNFK00071445630
Model	Townstar	Cylinder Capacity	1.332 ^{cm³}
Model Versions	Acenta L1H1 DIG-T 130 MT	Transmission Type	Handmatig geschakelde transmissie
Body Type	VAN	First Admission	07-09-2023
Color	White	Odometer	73.242 ^{Km}
Paint Type	Matte	Numer Of Keys	2
Production Year	2023	Interior	Grey
KW	96	Number Headrests	2

Images





Accessories

ABS

Airbags

Audio System

Bluetooth car kit

Central door locking

Cruise control

Electric windows front

Electrically adjustable exterior mirrors

Floor plate

Manual air conditioning

Rear parking sensors

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 ^{mm}	Imperial	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	5 ^{mm}	Continental	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	4 ^{mm}	Imperial	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	5 ^{mm}	Continental	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Fully Fledged					

Damages



Damage Part

Skirt - Left

Damage Type

Dent(s)

Repair Type

Panelbeating
& Spray

Acceptable

No



Damage Part

Hood

Damage Type

Stonechipping

Repair Type

Acceptable

Acceptable

Yes



Damage Part

Bumper - Front

Damage Type

Scratch(es)

Repair Type

Plastic Repair

Acceptable

No



Damage Part

Fender - Front Right

Damage Type

small dents / small scratches

Repair Type

Panelbeating
& Spray

Acceptable

No



Damage Part

Mirror - Rightside

Damage Type

Broken

Repair Type

Replace

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

small dents / small scratches

Repair Type

Panelbeating
& Spray

Acceptable

No



Damage Part

Bumper - Rear

Damage Type

Scratch(es)

Notes

Hoekje

Repair Type Acceptable

Plastic Repair No