



FORD KUGA: FY-768-PS

Vinnumber:	WF0FXXWPMFMU69168	Versionname:	FORD KUGA 1.5 EcoBlue 120 ch Vignale VP [5P] bvm 6-120CH-8cv (SUV)
First Registrationdate:	15/04/2021	Fiscalpower:	
Expertise Mileage:	116941	Power Kw:	88
Bodytype:	SUV	Body colour:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Diesel	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Seats electric F L	
GPS big screen color		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Seats F heated		Seat cover lining	Lining Leather
Type of climate control	Autom climate control		

Tyres

	225/60/18/104 W			
Summer tyres:	Fr.L.	Hankook: 55%	Fr.R.	Hankook: 55%
	Re.L.	Hankook: 35%	Re.R.	Hankook: 35%
Tyre profile depth FL				4.5
Tyre profile depth FR				4.5
Tyre profile depth RL				5.8
Tyre profile depth RR				5.9
Tyre size FL				225/60 R 18 104 W
Tyre size FR				225/60 R 18 104 W
Tyre size RL				225/60 R 18 104 W
Tyre size RR				225/60 R 18 104 W
Tyre type FL				All seasons
Tyre type FR				All Seasons
Tyre type RL				All seasons
Tyre type RR				All Seasons
Tyre make FL				260
Tyre make FR				260
Tyre make RL				260
Tyre make RR				260

Assistance equipment

Interior, Stain, Cleaning





Interior trim, Missing, Replace



Floor mat F, Hole, Replace



Dashboard, Tear, Repair/replace (lump sum)



Glove box R, Scratch(es), Repair/replace (lump sum)



Steering wheel, Worn, Replace



Alloy rim FL, Scratch(es), Acceptable





Alloy rim RL, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair/replace (lump sum)



Wing FL, Scratch(es), Polish



Outside rear-view mirror housing L, Scratch(es), Polish



Door FL, Dent(s), Repair and paint (complete)



Door trim RL, Scratch(es), Paint



Wing RL, Dent(s), Repair and paint (complete)



Door RL, Scratch(es), Polish



Outer sill L, Scratch(es), Paint



Bumper F, Broken, Replace and paint



Headlight L, Scratch(es), Replace



Wing trim RR, Scratch(es), Acceptable



Door RR, Scratch(es), Paint



Wing FR, Scratch(es), Polish



Wing trim FR, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Bumper moulding R, Scratch(es), Paint



Historique Maintenance

Immatriculation: **FY-768-PS** Date de 1ère immatriculation: **15/04/2021**

Modèle: **Ford KUGA 1.5 EcoBlue 120 ch Vignale VP [5P] bvm 6-120CH-8cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
17/03/2026	109.685	NDZ PARIS	REVISION ET CLIM
	0		BALAIS ESSUIE GLACE AV AR
	0		LIQUIDE DE FREIN
15/10/2025	107.072	NDZ PARIS	REVISION
	0		DIVERS ECHAPPEMENT
	0		DURITE D EAU RPLT
	0		BATTERIE RPLT
25/08/2025	103.680	SANTEOL	DIAG
22/01/2025	86.897	NDZ PARIS	POMPE A EAU RPLT
	0		REVISION
13/06/2024	78.634	FLEET SOLUTIONS FRANCE	PURGE CIRCUIT FREIN CTRL
	0		DISQUES PLAQUETTES AV RPLT
19/04/2024	72.966	NDZ PARIS	DIVERS ELEC
05/10/2023	59.854	NDZ PARIS	REVISION ET AIR ET CARBURANT
20/10/2022	30.231	NDZ PARIS	BALAIS ESSUIE GLACE AV
	0		REVISION ET CLIM