



## FORD Mondeo: 2656-LTV

Vinnumber:	<b>WF0DXXWPCMK07589</b>	Versionname:	<b>2.0 Híbrido 138kW (187CV) Trend HEV Auto sedán</b>
First Registrationdate:	<b>12/11/2021</b>	Fiscalpower:	<b>138kW 4P automática</b>
Expertise Mileage:	<b>107957</b>	Power Kw:	
Bodytype:	<b>Berline</b>	Body colour:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Type of rims (mounted):	<b>Aluminium</b>
Transmission:			
Fueltype:	<b>Hybrid</b>		
Engine functioning:	<b>Yes</b>		
Battery functioning:	<b>Yes</b>		
Vehicle running:	<b>Yes</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Certificate of Conformity:	<b>No</b>		
Category:	<b>Passenger Car</b>		
Registration Certificate Car (BE):	<b>No</b>		

## Options

Number of keys total	<b>2</b>	Central consol F
Number keys remote	<b>2</b>	Rear parking sensors
GPS big screen color		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Steering wheel leather		
Radio multimedia		
Type of climate control	<b>Autom climate control</b>	

## Tyres

215/60/16/95 V				
Summer tyres:	Fr.L.	<b>Dunlop: 3 mm</b>	Fr.R.	<b>Dunlop: 3 mm</b>
	Re.L.	<b>Goodyear: 6 mm</b>	Re.R.	<b>Goodyear: 6 mm</b>
Tyre profile depth FL				<b>3.0</b>
Tyre profile depth FR				<b>3.0</b>
Tyre profile depth RL				<b>6.0</b>
Tyre profile depth RR				<b>6.0</b>
Tyre size FL				<b>215/60 R 16 95 V</b>
Tyre size FR				<b>215/60 R 16 95 V</b>
Tyre size RL				<b>215/60 R 16 99 V</b>
Tyre size RR				<b>215/60 R 16 99 V</b>
Tyre type FL				<b>Summer</b>
Tyre type FR				<b>Summer</b>
Tyre type RL				<b>Summer</b>
Tyre type RR				<b>Summer</b>
Tyre make FL				<b>257</b>
Tyre make FR				<b>257</b>
Tyre make RL				<b>259</b>
Tyre make RR				<b>259</b>

## Assistance equipment

Repair kit	<b>No</b>
------------	-----------

MOT certificate, Missing, Repair/replace (lump sum)



Registration document, Missing, Repair/replace (lump sum)



Wing RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Repair and paint (complete)



Tyre repair kit, Missing, Repair/replace (lump sum)



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Tyres, No damage, Check





