APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	BMW
Model / version:	2 SERIES ACTIVE TOURER
Vin:	WBA21EA0907N26925
Mileage:	107035
SOH:	
First registration:	30/10/2023
Color:	Piemont Rot


ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES

























VIN INFORMATION

depuis 07.23	Luxury Line	Look Luxury Line spécifique
pack Travel	liquide de climatisation R1234YF	norme anti-pollution Euro 6 RDE II
vitrage ar avec protection solaire	mesures CO2 étendues	système d'accès confort
rétroviseurs jour/nuit automatique, chauffants et rabattables électrique	système d'appel d'urgence légal	tuner DAB
câble de charge Professional	High Beam Assist	phares LED adaptifs
garnissage sièges simili-cuir "Veganza" perforé	fixation Isofix pour siège enfant	filet de séparation coffre
rétroviseur int jour/nuit automatique	chargeur sans fil	1499 cc (1,5 L) 100 KW (essence) / 80 kW (électrique)
7 vitesses à double embrayage	protection des piétons active	205/60 R 17 .. W
7 J x 17 Alu finition brillante	Active Guard	tableau de bord Luxury
Exterieur Line aluminium satiné (cadre vitres)	pré-équipement Driving Assistant Plus	pré-équipement volant chauffant
encarts intérieurs boiseries en eucalyptus à pores ouverts	toit ouvrant en verre panoramique électrique	galerie de pavillon aluminium satiné
AWD	spécifique Europe	2 couches métallisée
indicateur de pression des pneus		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×

Front seats heated:		**Steering wheel:**	
Electric windows:		**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Michelin	205/60/R17/93H	Winter	Aluminium	✗
Front right	5 mm	Michelin	205/60/R17/93H	Winter	Aluminium	✗
Rear left	5 mm	Michelin	205/60/R17/93H	Winter	Aluminium	✗
Rear right	5 mm	Michelin	205/60/R17/93H	Winter	Aluminium	✗

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Boot lid covering R	Stain
2	Bumper F	Dent(s) and scratch(es)
3	Alloy rim FL polished	Dent(s) and scratch(es)

Total: 3


ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1


DAMAGES DETAILS

1 - Boot lid covering R - Stain







2 - Bumper F - Dent(s) and scratch(es)










3 - Alloy rim FL polished - Dent(s) and scratch(es)




4 - Bodywork - Dent(s) and scratch(es) - Renta®



SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES