MACADAM








BMW 5 Reeks (MKL): 2CKC905

Vinnumber:	**WBA11AJ0X0CL25238**	Versionname:	**530d Touring (G31) 3.0d 286pk/cv 5p Aut.**
First Registrationdate:	**22/08/2022**	Fiscalpower:	
Expertise Mileage:	**167074**	Power Kw:	**210**
Bodytype:		Type of rims (mounted)	**Aluminium**
Gearbox:	**Automatic**		
Transmission:			
Fueltype:	**Hybrid Diesel**		
Maintenance	**OK**		
Maintenance	**7000.0**		
Battery functioning	**Yes**		
Type of rims (mounted)	**Aluminium**		
Certificate of Conformity	**Yes**		
Category	**Passenger Car**		
Registration Certificate Car (BE)	**Yes**		

Options

Number of keys total	**2**	Luggage cover	
GPS		Type of Tow bar	**Tow bar collapsible**
Type of Maintenance book	**Digital maintenance**		
Type of GPS storage	**HD**		

Tyres

Summer tyres:	**245/35/20/95 Y**			
	Fr.L.	**Bridgestone: 8 mm**	Fr.R.	**Bridgestone: 8 mm**
	Re.L.	**Goodyear: 6 mm**	Re.R.	**Goodyear: 6 mm**

Tyre profile depth FL	**8.0**
Tyre profile depth FR	**8.0**
Tyre profile depth RL	**6.0**
Tyre profile depth RR	**6.0**
Tyre size FL	**245/35 R 20 95 Y**
Tyre size FR	**245/35 R 20 95 Y**
Tyre size RL	**275/30 R 20 97 Y**
Tyre size RR	**275/30 R 20 97 Y**
Tyre type FL	**Summer**
Tyre type FR	**Summer**
Tyre type RL	**Summer**
Tyre type RR	**Summer**
Tyre make FL	**255**
Tyre make FR	**255**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Interior, Dirty, Cleaning
















Alloy rim FL polished, Scratch(es), Repair and paint (complete)








Alloy rim RL polished, Scratch(es), Repair and paint (complete)




Wing RL, Dent(s), Acceptable




Bumper R, Dent(s) and scratch(es), Repair and paint (complete)








Tailgate / Boot, Scratch(es), Acceptable





Wing FR, Repaired, Check




Door FR, Repaired, Check




Door RR, Repaired, Check




Wing RR, Repaired, Check




Alloy rim FR polished, Scratch(es), Repair and paint (complete)




Alloy rim RR polished, Scratch(es), Repair and paint (complete)






Bodywork, Paint measurement, Check



Onderhoudshistorie van: WBA11AJ0X0CL25238

ALPHABET

Kenteken	2CKC905
Merk Model	BMW 530d Touring (G31) 3.0d 286pk/cv 5p Aut.
Brandstofsoort	Diesel
Datum deel1	8/22/22

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
2/12/26	144,883	BMW/MINI service standaard omvang	Uitvoeren
2/12/26	144,883	BMW/MINI service voertuig-check	Uitvoeren
2/12/26	144,883	klein materiaal	
2/12/26	144,883	koelwatervloeistof	Bijvullen/-laden
2/12/26	144,883	ruitenwisserrubber achter	Vervangen
2/12/26	144,883	ruitenwisserrubber vooraan	Vervangen
2/12/26	144,883	ruitenwisservloeistof	Bijvullen/-laden
2/12/26	144,883	service brandstoffilter	Uitvoeren
2/12/26	144,883	service luchtfilter	Uitvoeren
2/12/26	144,883	service microfilter	Uitvoeren
2/12/26	144,883	service motorolie	Uitvoeren
2/12/26	144,883	testrit	Uitvoeren
8/5/25	121,671	BMW/MINI service standaard omvang	Uitvoeren
8/5/25	121,671	controle niveaus	Uitvoeren
8/5/25	121,671	klein materiaal	
8/5/25	121,671	remvloeistof	Bijvullen/-laden
5/12/25	114,123	controle niveaus	Uitvoeren
1/13/25	103,682	BMW/MINI service standaard omvang	Uitvoeren
1/13/25	103,682	controle niveaus	Uitvoeren
1/13/25	103,682	klein materiaal	
1/13/25	103,682	service microfilter	Uitvoeren
1/13/25	103,682	service motorolie	Uitvoeren
3/19/24	67,228	batterij	Vervangen
3/19/24	67,228	BMW/MINI voertuigcontrole	Uitvoeren
3/19/24	67,228	ruitenwisserrubber vooraan	Vervangen
3/19/24	67,228	service brandstoffilter	Uitvoeren
3/19/24	67,228	service luchtfilter	Uitvoeren
3/19/24	67,228	service microfilter	Uitvoeren
3/19/24	67,228	service motorolie	Uitvoeren
12/10/23	51,942	controle niveaus	Uitvoeren
7/6/23	33,513	batterij	Vervangen
7/6/23	33,513	ruitenwisserrubber vooraan	Vervangen
7/6/23	33,513	service microfilter	Uitvoeren
7/6/23	33,513	service motorolie	Uitvoeren
5/6/23	27,816	controle niveaus	Uitvoeren