

MACADAM



Volvo XC 60

Vinnnumber:	LYVUZK9VDNB013213	Versionname:	
First Registrationdate:	12/04/2022	Fiscalpower:	
Expertise Mileage:	109482	Power Kw:	
Bodytype:		Body colour:	Dark Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3427
Fueltype:	Hybrid Petrol		
Maintenance:	OK		
Maintenance:	+ 233 dagen		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Seats electric F L:	
Cruise Control:		Seats electric F R:	
Steering wheel multifunctional:		Sun Roof electric:	
Seats F heated:		Panoramic roof:	
Radio multimedia:		Luggage cover:	
Type of headlighting:	Headlighting Xenon	Front parking sensors:	
Type of GPS:	GPS big screen color	Rear parking sensors:	
Type of Lining:	Lining leather	Type of Tow bar:	Tow bar collapsible
Type of climate control:	Autom climate control		
Adaptive cruise control:			
Type of GPS storage:	HD		

Limited Technical Inspection


Tyres

235/55/19/105 V				
Summer tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Uniroyal: 7 mm	Re.R.	Uniroyal: 7 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				7.0
Tyre profile depth RR				7.0
Tyre size FL				235/55 R 19 105 V
Tyre size FR				235/55 R 19 105 V
Tyre size RL				235/55 R 19 105 Y
Tyre size RR				235/55 R 19 105 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Emergency spare wheel:	Yes	Jack:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT:	612,63
Alloy rim RL polished, Rust, Acceptable:	0,00



Alloy rim FL polished, Scratch(es), Repair and paint (complete)

204,21



Bumper trim R, Scratch(es), Acceptable

0,00



Alloy rim FR polished, Scratch(es), Repair and paint (complete)

204,21



Alloy rim RR polished, Scratch(es), Repair and paint (complete)

204,21

