# APPRAISAL REPORT



## IDENTIFICATION VEHICLE

| | |
|---|---|
| **Driver name:** | ASSE I |
| **Make:** | AUDI |
| **Model / version:** | A3 SPORTBACK |
| **Vin:** | WAUZZZGY2MA063272 |
| **Plate:** | 2ACU891 |
| **Mileage:** | 56021 |
| **SOH:** | |
| **First registration:** | 23/02/2021 |
| **Color:** | Mythos Black |

## ADDITIONAL INFORMATION


| | |
|---|---|
| **Category:** | |
| **Transmission:** | |
| **Interior color:** | |
| **Metallic paint:** | ? |
| **Type of lining:** | |
| **Board computer reset:** | ? |


## DOCUMENTS


| | |
|---|---|
| **Certificate of conformity:** | ✓ |
| **Registration certificate:** | ✓ |
| **Registration certificate 2:** | ✗ |
| **Insurance certificate:** | ? |
| **Maintenance book:** | |
| **Number of keys:** | 2 |
| **Original key:** | ✓ |


## PICTURES

































## VIN INFORMATION

| | | |
|---|---|---|
| 6 haut-parleurs | Téléphone | Transmission séquentielle |
| 6 rapports | Matière : alliage | Lettre repère (J) |
| Diamètre avant 16 | Diamètre arrière 16 | Largeur avant 7,5 |
| Largeur arrière 7,5 | Diamètre avant 16 | Diamètre arrière 16 |
| Hauteur avant 55 | Hauteur arrière 55 | Indice de vitesse avant V |
| Indice de vitesse arrière V | Largeur avant 205 | Largeur arrière 205 |
| Climatisation automatique | Climatisation réfrigérant 1234YF | Accoudoir central avant |
| Euro 6 | Métallisée vernissée | Freins avant à disques |
| Rétroviseur gauche asphérique | Volant cuir | Volant chauffant |
| Volant multifonction | Aide au stationnement avant | Aide au stationnement arrière |
| Assistance au parking | Caméra avant | Affichage lecture des panneaux de signalisation |
| Appel de secours | Pare-brise teinté dégradé | Airbag passager |
| Airbag passager désactivable | Freinage d'urgence assistée autonome (urbain) | depuis 11.20 |
| radio avec récepteur numérique | câble de charge pour prise domestique HH Type E/F (10A) | CABLE CH CEE 1P 16A |
| câble de charge pour station de recharge publique Mode 3 Type 2 (16A) | garnissage tissu Index | extincteur |
| 1395 cc (1,4 L) 110 KW (essence) / 180 KW (Total) | système de gonflage des pneus | batterie de démarrage ar |

suspension ar à 4 bras

réservoir à charbon actif (EVAP)

sidebag av/ar avec airbag pour la tête et airbag central av

FREINS AR 272X10

transmission hybride PHEV

## EQUIPMENT

| | | | |
|---|---|---|---|
| **Board computer:** | ? | **Central locking:** | ? |
| **Compressor:** | ✓ | **Cruise control:** | ? |
| **Gps:** | ? | **Power steering:** | ? |
| **Rear parking sensor:** | ? | **Repair kit:** | ✓ |
| **Front seats heated:** | ? | **Steering wheel:** | ? |
| **Electric windows:** | ? | **Climate control type:** | |
| **Headlighting type:** | | **Tow bar type:** | |
| **Charging cables:** | 1 | **Fast charging cables:** | 1 |

## TIRES

| Position | Depth | Brand | Dimensions | Type | Rims | Runflat |
|---|---|---|---|---|---|---|
| Front left | 7 mm | | | Winter | Aluminium | ? |
| Front right | 7 mm | | | Winter | Aluminium | ? |
| Rear left | 7 mm | | | Winter | Aluminium | ? |
| Rear right | 7 mm | | | Winter | Aluminium | ? |

## DAMAGES SUMMARY

**NOT ACCEPTABLE / TO BE INVOICED**

| # | Location | Damage type |
|---|---|---|
| 1 | Certificate of registration 2 | Missing |
| 3 | Alloy rim FL | Scratch(es) |
| 4 | Door RL | Scratch(es) |
| 5 | Bumper R | Scratch(es) |
| 6 | Alloy rim RR | Scratch(es) |
| 7 | Alloy rim FR | Scratch(es) |

**Total: 6**

**ACCEPTABLE / NOT TO BE INVOICED**

| # | Location | Damage type | Renta® | Repaired | Already invoiced |
|---|---|---|---|---|---|
| 2 | Bodywork | Dent(s) and scratch(es) | ✓ | ✗ | ✗ |

**Total: 1**

## DAMAGES DETAILS

**1** - Certificate of registration 2 - Missing






**3** - Alloy rim FL - Scratch(es)




**4** - Door RL - Scratch(es)




**5** - Bumper R - Scratch(es)






**6** - Alloy rim RR - Scratch(es)




**7** - Alloy rim FR - Scratch(es)









**2** - Bodywork - Dent(s) and scratch(es) - Renta®

















## SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

**Expert**

21/10/2026 12:02

