

2-EDQ-055

2-EDQ-055 · Acenta L1H1 DIG-T 130 MT · 6 August 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EDQ-055	Fuel Type	Gasoline
Manufacturer	NISSAN	VIN	VNVNFK00771445625
Model	Townstar	Cylinder Capacity	1.332 ^{cm3}
Model Versions	Acenta L1H1 DIG-T 130 MT	Transmission Type	Handmatig geschakelde transmissie
Body Type	VAN	First Admission	07-09-2023
Color	White	Odometer	61.690 ^{Km}
Paint Type	Matte	Numer Of Keys	2
Production Year	2023	Interior	Darkgrey
KW	96	Number Headrests	2

Images





Accessories

ABS

Airbags

Audio System

Central door locking

Electric windows front

Manual air conditioning

Rear parking sensors

Condition

Condition exterior Adequate

Condition interior Adequate

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	4 ^{mm}	Continental	205 ^{mm}	60 ^{mm}	16 ^{inch}	Summer
Front Right	2 ^{mm}	Delinte	205 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	4 ^{mm}	Continental	205 ^{mm}	60 ^{mm}	16 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part

Drivers seat



Damage Type

Burned

Repair Type

Replace

Acceptable

No



Damage Part

Bumper - Rear



Damage Type

Dislocated / Loose

Repair Type

Repair

Acceptable

No



Damage Part

Bumper - Front



Damage Type

Scratch(es)

Repair Type

Plastic Repair

Acceptable

No



Damage Part
Frontdoor – Left

Damage Type
Dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
Bumper – Rear

Damage Type
Small scratch(es)

Repair Type
Acceptable

Acceptable
Yes



Damage Part
Cargodoor – Right

Damage Type
Dent(s)

Repair Type
Panelbeating &
Spotrepair

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Cargodoor - Left	Dent(s)	Panelbeating & Spotrepair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Dislocated / Loose	due to an empty tank the vehicle fell down - causing several errors. The tank was filled afterwards	Acceptable	Yes