

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	312981
License plate	2BGG982
Vehicle identification number	WBA31AC0205U46503
Dossier	2021186064
Make	BMW X1 sDrive 16d 85kW Aut.
Mileage	85687
First registration	15/11/2021
client availability date	15/05/2026
inspectionDate	22/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
139	Bumper Rear / Spoiler / Replace	N
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
77	Side View Mirror Left / Shell / Replace Not Painted	N
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
124	Light / Rear left / Replace	Y
153	Rear Bonnet // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
210	Door Front Right // Smart Repair Small	Y
217	Door Front Right / Trim / Replace	Y
227	Side View Mirror Right / Shell / Replace Not Painted	Y
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
569	Dashboard / Steering Wheel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	Y

## Damage Pictures




Windshield // Repair-glass damage




Wing Front right // Polish-Chemical reaction



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Roof // Polish-scratch



Rear Bonnet // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear left / Replace-scratch



Door Front Right / Trim / Replace-scratch



Side View Mirror Right / Shell / Replace Not Painted-scratch




Front Bonnet // Polish-scratch



Wheel Alloy Front Left // Repair-scratch



Side View Mirror Left / Shell / Replace Not Painted-scratch




Door Rear Left // Polish-scratch




Wing Rear Left // Polish-scratch



Front Left Door Interior Coating // Replace Completely-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Door Front Right // Smart Repair Small-dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Repair & Painting-scratch + dent



Bumper Rear / Spoiler / Replace-scratch + dent