

MACADAM ITALY S.R.L. Piazza Belgioioso, 2 - 20121 Milano (MI) Tel. - Fax Piva: 12729790969				Report No.		Expert's report for Alphabet Italia				Type of insurance Perizia						
				Policyholder				Opposite party				Opposite party company				
				Operation 2026		Claim number			Code / Agency				Date accident 30/06/2026			
				Expert code			Adjuster code			Policy number			Injured person can recover the VAT			
Date assignment 30/06/2026		Date first survey 03/07/2026		Place VILLORBA		C/O	Repairs			Photo	Lien in favor of			Expiry date		
Ownership certificate Alphabet Italia - Via Romano Guardini 24 38121 Trento (TN)												Formerly plate				
Lessee / Co-owner												Date of overhaul				
Vehicle (Brand - Model - Version) MERCEDES-BENZ GLB GLB 200 d Automatic 4MATIC Business Extr							Plate GK107FX		Vin Chassis W1N2476131W193190				First Registration 16/05/2022			
Usage status NON CONOSCIUTO		Km 136119	Tyres % 50		Color NERO		Type of enamel METALLIZED/DOUBLE			Consistency of damage		Type of Expert's report NOT DEFINITIVE				
Equipment																
Approval code		For commercial vehicles	Carrying Qls 0	Tare, Q 0	Wheelbase	Seats No. 0	Axles 0									
Commercial value (C)		Wrecked car value		Value by difference		Ancillary expenses										
Damaged items / restoration operations							SR		LA		VE		ME	D.M. S.C.	Costs of spare parts * (VAT excluded)	
							Dif	Time	Dif	Time	Dif	Time	Time			
1	A0999064601	Fanalino lat. retrovisore est.				R	S		S		S					
1	A2478800905	Front wheel arch trim				R	S		S		S					
1	A2479063700	Headlight				L	S		S		S					
1	A2478857800	Front bumper lower cladding					S		S		S					
1	A2478800306	Front bumper grille					S		S		S					
1	A2478855700	Rear bumper lower cladding					S		S		S					
1	24788029009999	Front bumper					G		G		G					
1	A24779006889999	Rear roof spoiler					G		L		G					
1	A2477207606	Front door				R	M		M		M					
1	A2477300404	Rear door				R	L				M					
1	A2477300304	Rear door				L	L				L					
1	A24788096009999	Rear bumper upper part					L		L		L					
1	A2478805307	Rear bumper lower part					L		L		L					
1	Codice Ricambio	Faro post est - PRM				L										
1	Codice Ricambio	cerchio post sx														
1	Codice Ricambio	Riparazione volante														

New for old value (N)	Remarks Pneum. Michelin 215/65 R17.
-----------------------	---

ALPHABET

Telaio W1N2476131W193190

GK107FX

MERCEDES-BENZ GLB GLB 200 d Automatic 4MATIC Business Extr sports utility vehicle 150CV 5P automatico

Current Odo (Time of Ma	Maintenance Request	Service Type Descriptio	Maintenance Job Description
25.000	03/05/23	Tagliando a 20 000 km	Tagliando a 20 000 km
51.800	05/03/24	Tagliando a 60 000 km	Tagliando a 60 000 km
79.920	24/02/25	Tagliando a 80 000 km	Tagliando a 80 000 km
102.000	04/09/25	Tagliando a 100 000 km	Tagliando a 100 000 km
130.099	06/05/26	Maintenance	Revisione Periodica MTC
130.099	06/05/26	Maintenance	Revisione Periodica MTC mo
134.000	22/06/26	Tagliando a 135 000 km	Tagliando a 135 000 km