


2-FCF-991



2-FCF-991 · FR 1,0L TSI 110HP DSG KJ75RZ E05 · 28 July 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FCF-991	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJXRR116899
Model	Arona	Cylinder Capacity	999 ^{cm3}
Model Versions	FR 1,0L TSI 110HP DSG KJ75RZ E05	Transmission Type	Automatisch geschakelde Transmissie
		First Admission	22-03-2024
Body Type	5 door hatchback	Odometer	104.749 ^{Km}
Color	Black	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
KW	85		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Delinte	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Left	3 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Front Right	2 ^{mm}	Delinte	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Rear Right	3 ^{mm}	Goodyear	205 ^{mm}	55 ^{mm}	17 ^{inch}	Summer
Spare Tire Type	None					

Damages



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Signallight broken	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Left	Small dent(s)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Roof	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Tailgate	Scratch(es)	Spoiler	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Broken	Antenne	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Scratch(es)	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Replace	No



Damage Part

Damage Type

Repair Type


Acceptable

Bumper - Front

Scratch(es)

Spray

No



Damage Part

Damage Type

Repair Type


Acceptable

Frontdoor - Left

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type


Acceptable

Reardoor - Left

Small dent(s)

Acceptable

Yes



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Rear

Small scratch(es)

Acceptable

Yes