

» Overview

Order number: 1002415641
Order completed: 17.04.2026 14:49
Report number: 10447009
VIN: WAUZZZFY5N2042705



Front Left 3/4



Rear Right 3/4



Mileage



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Audi
Model:	Q5
Manufacturers and type code:	0588 / BYQ
Date of first registration:	25.04.2022
Mileage:	46,285 km
Proof of mileage:	ReadOff
Exterior colour:	Mythossschwarz Metallic
Roof colour:	Mythossschwarz Metallic
Propulsion:	4 Wheel-drive
Fuel:	Diesel
Engine size (cc):	3,000 ccm
Performance:	210 kW (286 PS)
Length:	
Height:	
Width:	
Permitted total weight:	
Wheelbase:	
Number of powered axles:	2
Cylinders:	6
Euronorm:	Euro 6
Number of doors:	4
Number of seats:	5
Gearbox:	Automatic 8-speed
Upholstery type:	Lining leather
Interior colour:	schwarz-schwarz/schwarz-schwarz/schwarz/titangrau
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	04.2027
Registration certificate available:	Yes
Registration certificate received:	No
License plate:	None
Maintenance book:	Digital
Maintenance:	Not testable
Maintenance last date:	
Maintenance last mileage:	
Remainder until next maintenance:	14,600 KM



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

3-zone deluxe automatic air conditioning	Data module, Europe
48-V electric system	Daytime running lights
4-way lumbar support for the front seats	Deselection of Audi phone box
6-cyl. turbo diesel engine 3.0 l/210 kW V6 TDI common rail base engine is T7V/T2P	Diesel engine
6-cylinder diesel engine 3.0 l unit 059.P	Digital radio reception
Accent surfaces, Matt Black	Direct control code
AdBlue tank with increased capacity	Disc brakes in front, 17-inch (ECE)
Adhesive film	Disc brakes in rear, 17-inch (ECE)
Ambient Lighting package	Door sill trims with aluminum inlays, front, illuminated, S logo
Assist package City	Driver and front passenger airbag with front passenger airbag deactivation
Audi active lane assist	Driving on the right
Audi adaptive cruise control	Electric auxiliary air heater
Audi AG	Electromechanical parking brake
Audi connect emergency call & service with Audi connect remote & control	Electromechanical power steering
Audi connect navigation & infotainment	Electronic immobilizer
Audi drive select	Emission standard EU6 AP
Audi pre sense city	Equipment options subset for Germany
Audi pre sense rear	Extended pedestrian protection
Audi smartphone interface	Exterior mirror housings in body color
Audi sound system	Exterior mirrors, power-adjustable, heated and folding, auto- dimming on both sides, with memory feature
Audi virtual cockpit plus	Filler neck module 1 without insert
Axial and vertical adjustable steering column	First-aid kit with warning triangle and high-visibility vests
Basic	Floor mats, front and rear
Basic equipment variant	Front head restraints
Battery 380 A (68 Ah)	Front seats, electrically adjustable with memory function for driver seat and exterior mirrors
Belt-driven integrated starter alternator 48 V 110 - 250 A	Front seats, electrically adjustable with memory function for the driver seat
Beverage holders	Fuel system for diesel engine
Black roof rails with roof rack detection system	Fuel tank with increased capacity
Black Styling package	Gearshift/selector lever handle
Bluetooth interface	Headliner in Black fabric
Business package	Head-up Display
Camera-based traffic sign recognition	High-beam control
Carrier frequency 433.92 MHz-434.42 Mhz	Increase in initial standard fuel filling
Category 0	Inlays, Micrometallic, Silver
Child Safety package	Installation parts for six-cylinder engine
Child-proof lock, electrically operated	Instrument cluster, km/h speedometer
Comfort center armrest, front	Interior mirror, automatically dimming, frameless
Control code	ISOFIX child seat mounting and top tether for the outer rear seats
Control of series production	ISOFIX child seat mounting for the front passenger seat
Convenience key, without Safelock	Labels in English and German
Country group A	



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

Leather steering wheel, 3-spoke with multifunction plus	Side airbags, front and rear and head airbag system
Leather/mono.pur 550 artificial leather combination	Side and rear windows in heat-insulating glass
LED headlamps	Side assist
LED rear lights	Special identification label (EU)
Left exterior mirror, aspherical	Sport suspension
Left-hand drive	Sportsback
Loading floor	Standard
Loading sill protector, stainless steel	Standard climatic zones
Luggage compartment cover	Standard manufacturing sequence
Luggage compartment lid, electrically opening and closing	Standard pedal cluster
Luggage compartment mat	Standard seats in front
Manual in German	Standard suspension
Mild hybrid	Standard wheel bolts
MMI navigation plus with MMI touch	Standard-production quality
Model name as per new output designation	Start-stop system
No self-collection	Storage and Luggage Compartment package
No special edition	Sun visor on driver and front passenger side
No special purpose vehicle, standard equipment	Sunshade, manual for the door windows, rear
Non-smoker's package	tiptronic
Not hot country	tiptronic
Operating permit, alteration	Tire pressure loss indicator
Parking system plus	Tire repair kit
Part set without country-specific prescriptive standard	Tires 235/55 R19 101W
Partition net	Tires without specification of tire brand
Passenger car design	Tour assistance package
Preparation for functions on demand	Transit coating (type 2)
Preparation for trailer hitch	Two-tone horn
Privacy glass (dark-tinted windows)	Type approval country Germany
Production wheels	Vehicle class differentiation -FY0/FYF-
quattro	Vehicle tool kit (without vehicle jack)
quattro with self-locking center differential	Vehicles with special upgrade measures
Rear seat bench plus	Weight category front axle weight range 8
Rear trim panel (ECE)	Weight range 8 installation control only, no requirement forecast
Refrigerant R1234yf	Wheels, 10-spoke, 7.0J x 17, 235/65 R17 winter tires
Regional code " ECE " for radio	Wheels, 5-spoke V, Graphite Gray, gloss turned finish, 8.0J x 19, 235/55 R19 tires
Reinforced bumpers	Windshield with heat-reflecting glass and acoustic glass
Reversing camera	With multifunction camera
Right exterior mirror, aspherical	With special labels safety certificates for Germany
Roof spoiler	Without acoustic vehicle alerting system
S line	Without additional front underbody guard
Seat belt reminder	Without additional warning lights
Seat heating, front	Without antenna amplifier
Service indicator 30 000 km or 1 year (variable)	



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

Without auxiliary heater/parking heater
Without Car2X
Without charging cable for public charging (AC), mode 3
Without danger alarm system
Without decorative films/emoles
Without electric motor (hybrid)
Without fire extinguisher
Without front license plate carrier
Without garage door opener
Without headlamp washer system
Without ignition/starter switch locking system, without steering lock
Without integrated toll system
Without leather
Without locking and starting systems
Without mains cable for domestic connector for the e-tron charging system
Without mains cable for industrial connector for the e-tron charging system
Without preconditioning
Without preparation for VTS (vehicle tracking system)
Without roof insert (standard roof)
Without seat ventilation/massage seat
Without special body measures
Without step
Without vehicle inlet
Without wall mount



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Pirelli	Front	Left	Winter	Aluminium	235/65 R 17 104 H	3.0 mm
Pirelli	Front	Right	Winter	Aluminium	235/65 R 17 104 H	3.0 mm
Pirelli	Rear	Left	Winter	Aluminium	235/65 R 17 104 H	3.5 mm
Pirelli	Rear	Right	Winter	Aluminium	235/65 R 17 104 H	3.5 mm

Permitted: Yes

Roadworthy: Yes

UNMOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Continental			Summer	Aluminium	235/55 R 19 101 W	4.0 mm
Continental			Summer	Aluminium	235/55 R 19 101 W	5.0 mm
Continental			Summer	Aluminium	235/55 R 19 101 W	5.0 mm
Continental			Summer	Aluminium	235/55 R 19 101 W	4.0 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Toolkit present: Yes

Repair kit present: Yes

Repair kit expiration date: 09.2026

Compressor present: Yes



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

» Devaluation Factors

Nr	Location	Damage type	Repair type
1	Bumper F	Deformed / Strained	Replace and paint
2	Tyres	Worn	Replace
3	Bumper spoiler F	Deformed / Strained	Replace
4	Preparationtime plastic painting	Paint preparation	Execute
5	Warning indicator	Lights up	Diagnosis Damage extension possible

» Usage Damages

Nr	Location	Damage type	Repair type
1	Wing FR	Dent(s) and scratch(es)	Acceptable
2	Door RR	Dent(s) and scratch(es)	Acceptable



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

» Commercial devaluation

Accidental vehicle:	Yes
Known previous damages:	No
Previous damages detectable:	Yes
Repainting present:	No
Paint thickness measurement performed:	Yes - no abnormalities/deviations

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.



Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WAUZZZFY5N2042705

VIN checked and matches documentation

Vehicle condition:

Dirty

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

Yes

Testdrive carried out:

Yes

Engine test carried out:

Yes



Assessment


- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026

» Remarks

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures




Front Left 3/4



Front Right 3/4



Rear Left 3/4




Rear Right 3/4



Mileage



Tools




Sill outer L




Sill outer R




Chassis nr




Wheel FL



Wheel FR



Wheel RL



Wheel RR



Additional wheel 1



Additional wheel 2




Additional wheel 3




Additional wheel 4



Central console



Engine compartment



Documents


Assessment

- Vehicle Inspection Report -

Number: 10447009
From: 17.04.2026



Interior arrangement



Registration Certificate




Tyres in vehicle



History Maintenance



Interior - front



Interior - rear



Tirefit expiration date



Underbody scan



GPS/Radio

» Devaluation Damages

DEVALUATION FACTORS



1 - Bumper F - Deformed / Strained - Replace and paint



2 - Tyres - Worn - Replace



3 - Bumper spoiler F - Deformed / Strained - Replace



4 - Preparationtime plastic painting - Paint preparation - Execute

5 - Warning indicator - Lights up - Diagnosis
Damage extension possible



USAGE DAMAGES

1 - Wing FR - Dent(s) and scratch(es) - Acceptable



2 - Door RR - Dent(s) and scratch(es) - Acceptable

