



**Volkswagen ID.3: R620FG**

Vinnnumber:	<b>VWVZZZE1ZN8005945</b>	Versionname:	<b>ID.3 107kW / 62kWH Pro automaat</b>
First Registrationdate:	<b>29/08/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>41431</b>	Power Kw:	<b>107</b>
Bodytype:		Body colour:	<b>Mangan Grey metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Electric</b>	Parking lot:	<b>529</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Rear parking sensors
GPS		
Autom climate control		
Radio multimedia		

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 18 / 55 / T / Aluminium	4,0 mm	Goodyear	Summer
	Right	215 / 55 / 18 / 55 / T / Aluminium	4,1 mm	Goodyear	Summer
Rear	Left	215 / 55 / 18 / 55 / T / Aluminium	4,0 mm	Goodyear	Summer
	Right	215 / 55 / 18 / 55 / T / Aluminium	4,8 mm	Goodyear	Summer


**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

**Door RL, Scratch(es), Repair and paint (complete)**



**Wing FL, Dent(s) and scratch(es), Repair and paint (complete)**




**Bumper F, Scratch(es), Repair and paint (complete)**



Door RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)



Rear spoiler, Scratch(es), Repair and paint (complete)



Tailgate / Boot, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



<b>Kenteken</b>	R620FG
<b>Merk Model</b>	Volkswagen ID.3 107kW / 62kWH Pro automaat
<b>Brandstofsoort</b>	Elektrisch
<b>Datum deel1</b>	29-08-22

Datum reparatie	Kilometerstand	Reparatie omschrijving
01-05-26	39.569	Reparatie band(en)