MACADAM









SKODA OCTAVIA COMBI: GP-367-AR

Vinnumber:	**TMBJG8NX8PY042237**	Versionname:	**SKODA OCTAVIA COMBI 2.0 TDI 116 BVM6 Business VF [5P] 6-116CH-6cv (break)**
First Registrationdate:	**22/05/2023**	Fiscalpower:	
Expertise Mileage:	**166000**	Power Kw:	**85**
Bodytype:	**Break**	Body colour	**Grey**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:	**Front**	Interior colour	**Grey**
Fueltype:	**Diesel**	Type of rims (mounted)	**Aluminium**
Engine functioning	**Yes**	Dashboard color	**Black**
Battery functioning	**Yes**		
Vehicle running	**Yes**		
Number of doors	**5**		
Number of seats	**2**		
Number head rests	**2**		
Type of rims (mounted)	**Aluminium**		
Category	**VS**		

Options

Number of keys total	**2**	Radio	
Number keys remote	**2**	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Rear view camera	
Steering wheel leather		Seat cover lining	**Lining Other**
Type of climate control	**Autom climate control**		

Tyres

Summer tyres:	**205/60/16/96 V**			
	Fr.L.	**Goodyear: 75%**	Fr.R.	**Goodyear: 75%**
	Re.L.	**Goodyear: 25%**	Re.R.	**Goodyear: 25%**

Tyre profile depth FL	**3.4**
Tyre profile depth FR	**3.3**
Tyre profile depth RL	**6.5**
Tyre profile depth RR	**6.4**
Tyre size FL	**205/60 R 16 96 V**
Tyre size FR	**205/60 R 16 96 V**
Tyre size RL	**205/60 R 16 96 V**
Tyre size RR	**205/60 R 16 96 V**
Tyre type FL	**All seasons**
Tyre type FR	**All Seasons**
Tyre type RL	**All seasons**
Tyre type RR	**All Seasons**
Tyre make FL	**259**
Tyre make FR	**259**
Tyre make RL	**259**
Tyre make RR	**259**

Assistance equipment

Spare wheel	**Yes**	Jack	**Yes**

Seat cover FL, Stain, Cleaning




Floor mat F, Tear, Repair/replace (lump sum)




Tyre FL, Out of tolerance, Replace




Alloy rim FR, Scratch(es), Repair/replace (lump sum)





Tyre FR, Out of tolerance, Replace




Outer sill L, Dent(s) and scratch(es), Repair and paint (complete)






Door FL, Scratch(es), Paint





Bumper R, Scratch(es), Acceptable




ALPHABET

Historique Maintenance

Immatriculation: **GP-367-AR** Date de 1ère immatriculation: **22/05/2023**

Modèle: **Skoda OCTAVIA COMBI 2.0 TDI 116 BVM6 Business VF [5P] 6-116CH-6cv (break)**

Date	Kilométrage	Fournisseur	Descriptif
16/06/2026	155.612	JOSE CAUVIN SA	ADBLUE
			DISQUES PLAQUETTES AV RPLT
			BALAIS ESSUIE GLACE AV AR
			LIQUIDE DE FREIN
			DISQUES PLAQUETTES AR RPLT
			REVISION
27/11/2025	120.561	GARAGE DU CENTRE	REVISION
			PILE DE CLE RPLT
			ADBLUE
31/10/2025	118.001	CONTITRADE FRANCE	REMPLACEMENT PNEUS 4 SAISONS
22/04/2025	91.150	GARAGE DU CENTRE	ADBLUE
			PILE DE CLE RPLT
			LIQUIDE LAVE GLACE
			REVISION ET CLIM ET AIR ET CARBURANT
24/12/2024	72.005	CONTITRADE FRANCE	PERMUTATIONS PNEUS
12/09/2024	60.440	GARAGE DU CENTRE	REVISION
			LIQUIDE DE FREIN
			ADBLUE
			DIVERS FILTRE
			PLAQUETTES AR RPLT
			PLAQUETTES AV RPLT
16/04/2024	32.381	GARAGE DU CENTRE	REVISION
			ADBLUE
05/04/2024	29.250	CONTITRADE FRANCE	PERMUTATIONS PNEUS
12/01/2024	16.929	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER