MACADAM










Peugeot 2008: R876DX

Vinnumber:	**VR3UKZKXZNJ695106**	Versionname:	**e-2008 100kW/ 50kWh Allure Pack**
First Registrationdate:	**11/08/2022**	Fiscalpower:	
Expertise Mileage:	**196854**	Power Kw:	**100**
Bodytype:		Body colour	**Noir Perla Nera metaallak**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**693**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Lining semi-leather	
Autom climate control		Rear parking sensors	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 60 / 17 / 100 / V / Aluminium	3,9 mm	Vredestein	All season
	Right	215 / 60 / 17 / 100 / V / Aluminium	3,0 mm	Vredestein	All season
Rear	Left	215 / 60 / 17 / 100 / V / Aluminium	5,8 mm	Vredestein	All season
	Right	215 / 60 / 17 / 100 / V / Aluminium	5,8 mm	Vredestein	All season

Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Full-screen GPS, Not functioning (well), Replace



Seat cover FL, Burned, Replace




Interior, Stain, Cleaning






Wing FL, Scratch(es), Repair and paint (complete)




Door FL, Dent(s) and scratch(es), Repair and paint (complete)






Door RL, Scratch(es), Repair and paint (complete)




Bumper moulding F, Scratch(es), Replace and paint






Bumper trim F, Scratch(es), Replace






Bonnet, Scratch(es), Repair and paint (complete)




Door RR, Scratch(es), Repair and paint (complete)




Door FR, Scratch(es), Repair and paint (complete)




Wing FR, Dent(s), Paintless dent repair




Internal boot lining R, Scratch(es), Replace




Boot lid covering R, Scratch(es), Replace





Bumper corner RL, Scratch(es), Repair and paint (complete)





Bumper moulding R, Scratch(es), Replace and paint





Onderhoudshistorie van: VR3UKZKXZNJ695106

ALPHABET

Kenteken	R876DX
Merk Model	Peugeot e-2008 100kW/ 50kWh Allure Pack
Brandstofsoort	Elektrisch
Datum deel1	8/11/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
3/25/26	159,743	APK
3/25/26	159,743	Motor koelventilator
3/25/26	159,743	Onderhoudsbeurt
3/25/26	159,743	Remvloeistof
3/25/26	159,743	Ruitenwisserblad(en) voorzijde
3/25/26	159,743	Sleutelbatterij
3/25/26	159,743	Vervanging band
9/1/25	126,958	Onderhoudsbeurt
9/1/25	126,958	Remblokken achterzijde
9/1/25	126,958	Tankklep
9/1/25	126,958	Vervanging band
8/29/24	77,118	Onderhoudsbeurt
8/29/24	77,118	Vervanging band
7/17/23	42,731	Onderhoudsbeurt
3/3/23	21,281	Onderhoudsbeurt
11/15/22	11,427	Onderhoudsbeurt
9/19/22	0	Accu