

VOLKSWAGEN PASSAT VARIANT:

Vinnumber:	WVWZZZ3CZME086977	Versionname:	2.0 TDI 90kW DSG Style Business
First Registrationdate:	19/02/2021	Fiscalpower:	
Expertise Mileage:	149396	Power Kw:	90
Bodytype:		Body colour:	White
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	3307
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Panoramic roof	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	Tow bar collapsible
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Tyres

	215/55/17/92 H			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 92 H
Tyre size FR				215/55 R 17 92 H
Tyre size RL				215/55 R 17 92 H
Tyre size RR				215/55 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				265
Tyre make FR				265
Tyre make RL				265
Tyre make RR				265

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	965,58
Interior, Not original part, Replace	16,66




Door panel RL, Scratch(es), Smart repair 116,69



Bumper F, Scratch(es), Repair and paint (complete) 0,00




Scratch(es), Acceptable 0,00




Wing RL, Scratch(es), Acceptable 0,00



Bumper R, Dent(s) and scratch(es), Repair and paint (complete) 296,58



Tailgate / Boot, Dent(s), Acceptable 0,00



Rear window, Scratch(es), Polish 77,26



Wing RR, Bad repair, Check 0,00



Door RR, Bad repair, Check 0,00



Step R, Dent(s) and scratch(es), Repair and paint (complete) 161,81



Bodywork, Not original part, Remove lettering

0,00

