MACADAM










Polestar 2: N298KF

Vinnumber:	**LPSVSEGEKNL054272**	Versionname:	**Polestar 2 170kW/ 78kWh Single Motor Long Range**
First Registrationdate:	**10/11/2021**	Fiscalpower:	
Expertise Mileage:	**151913**	Power Kw:	**170**
Bodytype:		Body colour	**Magnesium (metallic)**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**1175**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Panoramic roof	
GPS		Rear parking sensors	
Autom climate control		Hook	
Radio multimedia		Rear view camera	

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	245 / 45 / 19 / 102 / Y / Aluminium	3,6 mm	Bridgestone	Summer
	Right	245 / 45 / 19 / 102 / Y / Aluminium	3,6 mm	Bridgestone	Summer
Rear	Left	245 / 45 / 19 / 102 / V / Aluminium	5,6 mm	Michelin	Summer
	Right	245 / 45 / 19 / 102 / V / Aluminium	5,4 mm	Michelin	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Door RR, Bad repair, Repair and paint (complete)




Wing RR, Repaired, Check



Tailgate / Boot, Scratch(es), Repair and paint (complete)





Bumper R, Repaired, Check



Onderhoudshistorie van: LPSVSEGEKNL054272

ALPHABET

Kenteken	N298KF
Merk Model	Polestar Polestar 2 170kW/ 78kWh Single Motor Long Range
Brandstofsoort	Elektrisch
Datum deel1	11/10/21

Datum reparatie	Kilometerstand	Reparatie omschrijving
10/24/25	116,382	APK
10/24/25	116,382	Onderhoudsbeurt
10/24/25	116,382	Ruitenwisserblad(en) voorzijde
2/5/25	93,741	Onderhoudsbeurt
2/5/25	93,741	Volvo Check slijtagedelen
2/5/25	93,986	Vervanging band
4/3/24	69,649	Reparatie band(en)
1/19/24	62,000	Ruitenwisserblad(en) voorzijde
1/12/24	61,890	Onderhoudsbeurt
1/12/24	61,890	Volvo Check slijtagedelen