



Skoda Octavia (UKL): 2DVX565

Vinnumber:	TMBJP8NX2PY123850	Versionname:	Octavia Combi Clever 1.0TSi 110pk/cv 5p
First Registrationdate:	10/07/2023	Fiscalpower:	
Expertise Mileage:	84764	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:	Petrol		
Maintenance	OK		
Maintenance	plus 12800 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	1	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

205/60/16/96 H				
Summer tyres:	Fr.L.	Vredestein: 2 mm	Fr.R.	Vredestein: 3 mm
	Re.L.	Vredestein: 4 mm	Re.R.	Vredestein: 4 mm
Tyre profile depth FL	2.0			
Tyre profile depth FR	3.0			
Tyre profile depth RL	4.0			
Tyre profile depth RR	4.0			
Tyre size FL	205/60 R 16 96 H			
Tyre size FR	205/60 R 16 96 H			
Tyre size RL	205/60 R 16 96 H			
Tyre size RR	205/60 R 16 96 H			
Tyre type FL	All seasons			
Tyre type FR	All Seasons			
Tyre type RL	All seasons			
Tyre type RR	All Seasons			
Tyre make FL	2480			
Tyre make FR	2480			
Tyre make RL	2480			
Tyre make RR	2480			

Assistance equipment

Spare wheel	Yes	Jack	Yes
Ignition key, Missing, Replace			



Seat cover FR, Stain, Cleaning



Bumper F, Scratch(es), Acceptable



Bonnet, Dent(s), Paintless dent repair



Door FL, Dent(s) and scratch(es), Repair and paint (complete)



Door RL, Dent(s) and scratch(es), Repair and paint (complete)




Tyre FL, Worn, Check



Shutter / cover R, Broken, Replace



Internal boot lining L, Scratch(es), Smart repair



Internal boot lining R, Scratch(es), Smart repair



Boot lid covering R, Broken, Replace



Bumper R, Scratch(es), Acceptable



Wing RR, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Kenteken	2DVX565
Merk Model	Skoda Octavia Combi Clever 1.0TSi 110pk/cv 5p
Brandstofsoort	Benzine
Datum deel1	7/10/23

Datum reparatie	Kilometerstand	Reparatie omschrijving	Bewerking
5/22/26	82,363	foutencodes uitlezen	Uitvoeren
1/30/26	67,561	diagnose	Uitvoeren
1/30/26	67,561	klein materiaal	N.v.t.
1/30/26	67,561	stekker jack/USB, kabel	Vervangen
1/15/26	66,526	batterij	Vervangen
1/15/26	66,526	bougie	Vervangen
1/15/26	66,526	Inspectie met olie vervanging (vast in	Uitvoeren
1/15/26	66,526	klein materiaal	
1/15/26	66,526	koelwatervloeistof	Bijvullen/-laden
1/15/26	66,526	luchtfiltre interieur	Vervangen
1/15/26	66,526	remvloeistof	Vervangen
1/15/26	66,526	ruitenwisserrubber achter	Vervangen
1/15/26	66,526	ruitenwisserrubber vooraan	Vervangen
1/15/26	66,526	ruitenwisservloeistof	Bijvullen/-laden
3/11/25	37,730	foutencodes uitlezen	Uitvoeren
3/11/25	37,730	Inspectie met olie vervanging (vast in	Uitvoeren
3/11/25	37,730	klein materiaal	
3/11/25	37,730	koelwatervloeistof	Bijvullen/-laden
3/11/25	37,730	ruitenwisservloeistof	Bijvullen/-laden