



Expertise

Protocol number: 46179477
Order No. / Reference: 26461244
Inspection date: 23 Jun 2026

Manufacturer: Audi
VIN: WAUZZZGA2MA034633

Model: Q2 35 TFSI S tronic



Vehicle details	
Manufacturer / Type / Model / Equipment	
Audi Q2 35 TFSI S tronic	
Vehicle Identification number	WAUZZZGA2MA034633
Mileage (Read)	7,286 km
First registration	7 Apr 2021
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Power / Engine displacement	110 kw / 1,498 ccm
Fuel type / Cylinder	Petrol / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Ibisweiss
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite



Vehicle details

Maintenance booklet / proof	digital proof / complete	Next maintenance in	27,700 km
Last service on / at	04/2025 at 5,736 km		
Key is / should be	2 / 2	FZG documents	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC184053
Previous damage / Accident	None detectable	Repainting	None detectable
Inspection conditions	sufficient	Lifting equipment / pit	No
Test drive	Not performed	Engine function test	Performed
Manufacturer key number/ type code number	0588 / BOM 00345		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	fine dust sticker	
Permitted total weight	1,870 kg	Empty weight	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R16 95V	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	215/60 R16 95V	Summer tyres on Light alloy	Bridgestone	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94V	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	215/55 R17 94V	Winter tyres on Light alloy	Bridgestone	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R19 100M	Summer tyres on Steel	Hankook	5 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Audi connect Emergency Call & Service
- Audi pre sense front
- Exterior mirror housings in body color
- Fabric headliner
- Decorative inlays diamond lacquer silver grey
- Electronic Differential Lock (EDS)
- Electronic Stability Program (ESP)
- Chassis: Standard chassis
- Windscreen with grey color stripe
- Velour floor mats
- Transmission: S tronic 7-speed
- Heated rear window
- Interior lighting
- Manual child lock
- Manual air conditioning (cools or heats the vehicle interior - air distribution and fan manually adjustable - manual recirculation mode - particle filter - dust and odor separating cabin air filter, which ensures a lower burden of dust particles and odors in the vehicle interior)
- Loading floor
- Steering wheel in 3-spoke design
- Non-smoking version
- Upholstery: Fabric script
- Radio: MMI Radio plus
- Seats, driver's seat height adjustable
- Start-stop system with recuperation
- Four lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking/remote key
- Airbag: Front side airbags and head airbag system
- Traction control (ASR)
- Audi connect Remote & Control
- Electrically adjustable/heated exterior mirrors
- Vehicle tool kit
- Rear roof spoiler in car color
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Driver information system
- Electric windows front and rear
- Remote key (without Safe-Lock)
- Adjustable speed limiter
- Tail lights
- rear window wiper
- Interior mirror, manually dimmable
- ISOFIX child seat attachment in the front, Top Tether and i-Size for the outer rear seats
- Headrests (2) height adjustable
- Rear headrests (3)
- Paintwork: Blade in car color
- Paint finish: Solid
- LED headlights
- Light and rain sensor
- Otto particulate filter
- Progressive steering
- Tire pressure monitoring system
- Seats: Rear seat backrest foldable
- 12-volt socket
- Warning and indicator lights
- thermal insulation glazing



Extra equipment

- Audi connect Navigation & Infotainment - 3 years (Navigation with Google Earth - Online traffic information - Online Point of Interest - Weather information - Wi-Fi hotspot - Calendar - Online news - Online media streaming - Destination input via myAudi)
- Function package (storage and luggage compartment package - lockable glove compartment - storage pocket on the back of the front seatbacks - storage compartment under the passenger seat - 12-volt socket in the rear center console - 12-volt socket in the trunk - luggage compartment tie-down system - trunk net - second luggage compartment light in the side panel - rear seatback, split-folding in a 40:20:40 ratio or fully foldable, with center armrest and cupholders)
- Comfort package seats (comfort center armrest front, adjustable in tilt and longitudinally sliding - front passenger seat in addition to driver's seat manually height-adjustable)
- Wheel: Aluminum cast wheels (4 pieces) in 5-spoke design (6.5 J x 16 with tires 215/60 R 16)
- Lane Departure Warning (within system limits, helps prevent unintentional lane departures. If the system is activated and ready, and the driver has not used the turn signal, the Lane Departure Warning helps prevent crossing detected lane markings by making corrective steering interventions. Additional steering wheel vibration can be set at the driver's request. Operating range from approximately 60 to a maximum of 250 km/h)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction plus
- Parking Assistance Package (Parking Aid Plus - Hill Start Assist - Rear View Camera)
- Assistance package Safety package (Audi side assist - Audi pre sense basic - in conjunction with optional parking aid plus or optional parking assistant including rear cross traffic assist)
- Package Function Package Tires (On-board tools and jack - Space-saving spare wheel)
- Comfort package plus (interior mirror automatically dimming, frameless - exterior mirrors electrically adjustable, heated and folding, automatically dimming on both sides - 4-way lumbar support for the front seats)
- Navigation package (navigation system with high-resolution 8.3-inch color display, online map updates, 3D map display, online traffic information, MMI search, MMI touch, natural language operation, detailed route information, convenient internet connection, Wi-Fi hotspot, country information, flash memory for music (10 GB), DVD drive (MP3, WMA, AAC, MPEG-4), AUX-IN)
- Telephone: Audi Smartphone Interface (Selected apps can be integrated via Android Auto or Apple CarPlay. - The Audi smartphone interface connects your smartphone to your Audi. It seamlessly integrates your smartphone content directly into the MMI display via USB. - Navigation, telephony, music, and selected third-party apps can be conveniently controlled via the MMI controller and voice control on your smartphone.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction
5	Interior	Interior - Soiled - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.



Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
(Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
(Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten möglich.
- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Wartungshistorie

(gemäß Auftraggeber Informationen)

Fahrgestellnummer: WAUZZZGA2MA034633
Hersteller / Modell: AUDI AUDI Q2 35 TFSI S tronic

Datum	KM-Stand	Beschreibung
10.04.2026	6.701	AU
28.04.2025	5.736	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges
30.04.2024	4.389	AU
31.03.2023	2.827	Bremsflüssigkeit; Bremsflüssigkeit ern; Motoröl b. Wartung; Ölfilter ern; Regelwartungsdienst; Wartung Sonstiges