MACADAM










Seat Leon: P584BD

Vinnumber:	**VSSZZZKLZNR019649**	Versionname:	**Leon 2.0 TDI 85kW Style Business Intense Sportstourer**
First Registrationdate:	**3/02/2022**	Fiscalpower:	
Expertise Mileage:	**184208**	Power Kw:	**85**
Bodytype:		Body colour	**Midnight Black - metallic**
Gearbox:	**MAN 6 VIT**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Diesel**	Parking lot	**1092**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS		Hook	
Autom climate control		Rear view camera	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 45 / 17 / 94 / Y / Aluminium	5,1 mm	Bridgestone	Summer
	Right	225 / 45 / 17 / 94 / Y / Aluminium	5,1 mm	Bridgestone	Summer
Rear	Left	225 / 45 / 17 / 94 / Y / Aluminium	4,2 mm	Bridgestone	Summer
	Right	225 / 45 / 17 / 94 / Y / Aluminium	4,5 mm	Bridgestone	Summer

Assistance equipment

Interior, Stain, Cleaning






Wing RL, Dent(s) and scratch(es), Repair and paint (complete)







Door RL, Bad repair, Repair and paint (complete)




Outside rear-view mirror housing L, Scratch(es), Replace and paint

Windscreen, Stone chip(s), Windscreen repair




Outer door handle FR, Scratch(es), Repair and paint (complete)





Wing RR, Dent(s) and scratch(es), Repair and paint (complete)






Door RR, Scratch(es), Repair and paint (complete)




Boot lid covering R, Scratch(es), Replace




Bumper R, Scratch(es), Repair and paint (complete)




Onderhoudshistorie van: VSSZZZKLZNR019649

ALPHABET

Kenteken	P584BD
Merk Model	Seat Leon 2.0 TDI 85kW Style Business Intense Sportstourer
Brandstofsoort	Diesel
Datum deel1	2/3/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
9/10/26	179,100	APK
9/10/26	179,100	Multiriem inclusief spanner
9/10/26	179,100	Onderhoudsbeurt
4/7/26	165,889	Dynamo
4/7/26	165,889	Multiriem controle
1/9/26	157,057	APK
1/9/26	157,057	Onderhoudsbeurt
1/9/26	157,057	Remblokken achterzijde
1/9/26	157,057	Remblokken voorzijde
1/9/26	157,057	Sleutelbatterij
7/18/25	139,212	Airco controle
7/18/25	139,212	Onderhoudsbeurt
7/18/25	139,212	Parkeersensor
7/18/25	139,212	Ruitenwisserblad(en) achterzijde
1/27/25	123,297	APK
1/27/25	123,297	Onderhoudsbeurt
1/27/25	123,297	Remvloeistof
1/27/25	123,297	Ruitenwisserblad(en) voorzijde
1/27/25	123,297	Vervanging band
10/30/24	115,896	Sleutel/Kaart
10/28/24	115,895	Brandstoffilter
10/28/24	115,895	Onderhoudsbeurt
10/28/24	115,895	Remblokken achterzijde
10/28/24	115,895	Remblokken voorzijde
10/28/24	115,895	Ruitenwisserblad(en) achterzijde
10/28/24	115,895	Sleutelbatterij
9/25/24	113,094	Vervanging band
8/8/24	108,895	Vervanging band
6/21/24	104,959	Reparatie band(en)
4/24/24	97,347	Onderhoudsbeurt
4/24/24	97,347	Sleutelbatterij
12/8/23	82,893	Brandstoffilter
12/8/23	82,893	Luchtfilter
12/8/23	82,893	Onderhoudsbeurt
12/8/23	82,893	Ruitenwisserblad(en) achterzijde
12/8/23	82,893	Ruitenwisserblad(en) voorzijde
12/8/23	82,893	Sleutelbatterij
4/21/23	58,711	Onderhoudsbeurt
9/15/22	32,054	Onderhoudsbeurt
3/21/22	6,335	Reparatie band(en)