



DS 7 CROSSBACK: FV-331-VT

Vinnumber:	VR1J45GBULY048115	Versionname:	DS DS 7 CROSSBACK E-TENSE 225 So Chic VP [5P] bva 8-225CH-10cv (SUV)
First Registrationdate:	14/12/2020	Fiscalpower:	
Expertise Mileage:	95969	Power Kw:	165
Bodytype:	SUV	Body colour:	White
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Sun Roof electric	
GPS big screen color		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Rear view camera	
Type of climate control	Autom climate control	Seat cover lining	Lining Other

Tyres


	235/50/19/103 V			
Summer tyres:	Fr.L.	Michelin: 75%	Fr.R.	Michelin: 75%
	Re.L.	Michelin: 70%	Re.R.	Michelin: 80%
Tyre profile depth FL				3.5
Tyre profile depth FR				3.5
Tyre profile depth RL				3.7
Tyre profile depth RR				3.0
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Interior, Dirty, Cleaning



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Tyre FL, Out of tolerance, Replace



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Wing RL, Dent(s), Acceptable



Door RL, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Paint



Door RR, Scratch(es), Polish



Luggage compartment cover, Missing, Replace



Charging cable (normal), Missing, Replace



Rubber seal for boot lid, Tear, Replace




Tailgate / Boot, Scratch(es), Paint



Bumper R, Scratch(es), Paint



Fog light RR, Broken, Replace



Historique Maintenance

Immatriculation: FV-331-VT Date de 1ère immatriculation: 14/12/2020

Modèle: DS 7 CROSSBACK E-TENSE 225 So Chic VP [5P] bva 8-225CH-10cv (SUV)

Date	Kilométrage	Fournisseur	Descriptif
21/12/2025	84.672	STELLANTIS &YOU FRANCE SAS	RECYCLAGE
	0		REVISION
	0		DIVERS CLIM
	0		BALAI ESSUIE GLACE AR
	0		BALAIS ESSUIE GLACE AV
	0		DISQUES PLAQUETTES AV RPLT
	0		BATTERIE RPLT
	0		FILTRE CLIM RPLT
	0		LIQUIDE DE FREIN
21/01/2025	66.014	EUROFLEET TYRES AND SERVICES	REPLACEMENT PNEUS ETE
26/07/2024	60.253	STELLANTIS &YOU FRANCE SAS	FILTRE A AIR RPLT
	0		REVISION
	0		BOITIER D ALLUMAGE RPLT
20/07/2023	41.087	STELLANTIS &YOU FRANCE SAS	REVISION ET CLIM
	0		LIQUIDE DE FREIN
	0		BALAIS ESSUIE GLACE AV AR
05/07/2023	40.085	EUROFLEET TYRES AND SERVICES	REPARATION DE ROUE
24/05/2022	22.228	STELLANTIS &YOU FRANCE SAS	BALAIS ESSUIE GLACE AV
	0		BOITIER D ALLUMAGE RPLT
	0		REVISION