



PEUGEOT 208: FN-519-MS

Vinnumber:	VR3UPHNKLT007082	Versionname:	PEUGEOT 208 Puretech 100 S&S Allure Business VP [5P] bvm 6-100CH-5cv (bi-corps)
First Registrationdate:	4/02/2020	Fiscalpower:	
Expertise Mileage:	38299	Power Kw:	75
Bodytype:	Berline	Body colour:	Light Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Interior colour:	Grey
Fueltype:	Petrol	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	2	Radio	
Number keys remote	2	Central consol F	
GPS big screen color		Luggage cover	
GPS storage		Headlights Xenon/LED/Laser	
GPS storage	HD	Rear parking sensors	
Windows electric F		Rear view camera	
Windows electric R		Seat cover lining	Lining Semi-leather
Cruise Control			
Steering wheel multifunctional			
Steering wheel leather			
Type of climate control	Autom climate control		

Tyres

	195/55/16/87 H			
Winter tyres:	Fr.L.	Michelin: 35%	Fr.R.	Michelin: 35%
	Re.L.	Michelin: 35%	Re.R.	Michelin: 35%
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				195/55 R 16 87 H
Tyre size FR				195/55 R 16 87 H
Tyre size RL				195/55 R 16 87 H
Tyre size RR				195/55 R 16 87 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Spare wheel	Yes	Jack	Yes
Inner door sill FR, Dent(s), Repair and paint (complete)			



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace




Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Paint



Outside rear-view mirror housing L, Scratch(es), Polish



Bumper F, Scratch(es), Paint





Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Polish



Wing RR, Dent(s), Repair and paint (complete)



Luggage cover stopper, Missing, Replace



Luggage cover stopper, Missing, Replace



Bumper R, Scratch(es), Polish



Historique Maintenance

Immatriculation: **FN-519-MS** Date de 1ère immatriculation: **04/02/2020**

Modèle: **Peugeot 208 Puretech 100 S&S Allure Business VP [5P] bvm 6-100CH-5cv (bi-corps)**

Date	Kilométrage	Fournisseur	Descriptif
10/03/2026	36.339	SAS GARAGE VENET	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		DIVERS CLIM
	0		COURROIE ACCESSOIRES RPLT
	0		DIVERS ELEC
	0		LIQUIDE DE FREIN
11/02/2025	28.954	SAS GARAGE VENET	DIVERS CLIM
	0		REVISION
	0		FILTRE CLIM RPLT
21/01/2025	28.810	DEKRA AUTOMOTIVE S.A	CONTROLE TECHNIQUE
16/01/2024	21.648	SAS A2R	BOITIER D ALLUMAGE RPLT
	0		DIVERS ELEC
	0		DIVERS CLIM
	0		RECYCLAGE
	0		REVISION
	0		FILTRE A AIR RPLT
	0		BALAIS ESSUIE GLACE AV
14/01/2024	20.852	FLEET SOLUTIONS FRANCE	GARDIENNAGE
08/11/2022	17.558	NORAUTO SAS (PRODUIT SPE)	PERMUTATIONS PNEUS
	0		GARDIENNAGE
20/07/2022	15.282	STELLANTIS &YOU FRANCE SAS	LIQUIDE DE FREIN
	0		RECYCLAGE
	0		BALAIS ESSUIE GLACE AV AR
	0		REVISION ET CLIM
13/04/2022	12.155	NORAUTO SAS (PRODUIT SPE)	PERMUTATIONS PNEUS
10/11/2021	8.459	CONTITRADE FRANCE	REMPLACEMENT PNEUS HIVER
16/06/2021	4.129	STELLANTIS &YOU FRANCE SAS	REVISION
	0		BALAIS ESSUIE GLACE AV
	0		BALAI ESSUIE GLACE AR
	0		FILTRE CLIM RPLT