



DS 7 CROSSBACK: FR-846-HG

Vinnumber:	VR1J45GBULY028458	Versionname:	DS DS 7 CROSSBACK E-TENSE 4x4 PERFORMANCE
First Registrationdate:	10/07/2020	Fiscalpower:	Line + VP [5P] bva 8-300CH-11cv (SUV)
Expertise Mileage:	123201	Power Kw:	221
Bodytype:	SUV	Body colour:	Black
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Interior colour:	Black
Fueltype:	Plug-in hybrid	Type of rims (mounted):	Aluminium
Engine functioning:	Yes	Dashboard color:	Black
Battery functioning:	Yes		
Vehicle running:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Category:	Passenger Car		

Options

Number of keys total	1	Radio	
Number keys remote	1	Central consol F	
GPS big screen color		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Steering wheel leather		Roof bar black	
Type of climate control	Autom climate control	Rear view camera	
		Seat cover lining	Lining Semi-leather
			Lining Alcantara

Tyres

	235/50/19/103 V			
Summer tyres:	Fr.L.	Michelin: 85%	Fr.R.	Michelin: 70%
	Re.L.	Michelin: 75%	Re.R.	Michelin: 80%
Tyre profile depth FL				2.5
Tyre profile depth FR				3.8
Tyre profile depth RL				3.3
Tyre profile depth RR				2.8
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Remote ignition key (no insert), Missing, Repair/replace (lump sum)



Malfunction indicator, Blinking, Check



Tyre FL, Out of tolerance, Replace



Tyre RL, Out of tolerance, Replace



Tyre RR, Out of tolerance, Replace



Tyre FR, Out of tolerance, Replace



Alloy rim FR bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Alloy rim RR bitone/polychrome, Scratch(es), Acceptable



Alloy rim RL bitone/polychrome, Scratch(es), Acceptable



Alloy rim FL bitone/polychrome, Scratch(es), Repair/replace (lump sum)



Door FL, Dent(s), Repair and paint (complete)



Wing RL, Scratch(es), Paint





Bumper F, Scratch(es), Paint



Bumper moulding F, Scratch(es), Replace



Door RR, Scratch(es), Paint



Door FR, Scratch(es), Paint



Wing FR, Scratch(es), Paint



Charging cable (normal), Missing, Replace



Rear light L, Waterinfiltration, Replace



Bumper R, Scratch(es), Paint



Tailgate / Boot, Scratch(es), Acceptable



Historique Maintenance

Immatriculation: **FR-846-HG** Date de 1ère immatriculation: **10/07/2020**

Modèle: **DS 7 CROSSBACK E-TENSE 4x4 PERFORMANCE Line + VP [5P] bva 8-300CH-11cv (SUV)**

Date	Kilométrage	Fournisseur	Descriptif
27/02/2026	121.502	STELLANTIS &YOU FRANCE SAS	BATTERIE RPLT
21/11/2025	116.648	STELLANTIS &YOU FRANCE SAS	RECYCLAGE
	0		REVISION
	0		BALAI ESSUIE GLACE AR
	0		FILTRE CLIM RPLT
	0		DIVERS CLIM
	0		BALAIS ESSUIE GLACE AV
03/12/2024	98.729	STELLANTIS &YOU FRANCE SAS	KIT ACCESSOIRES RPLT
	0		REVISION ET CLIM ET AIR ET BOUGIES
	0		BALAIS ESSUIE GLACE AV
25/01/2024	79.960	EUROFLEET TYRES AND SERVICES	REMPLACEMENT PNEUS ETE
10/01/2024	79.208	STELLANTIS &YOU FRANCE SAS	REVISION
	0		BALAIS ESSUIE GLACE AV
28/02/2023	61.290	STELLANTIS &YOU FRANCE SAS	REVISION ET CLIM ET AIR
	0		BOITIER D ALLUMAGE RPLT
	0		BALAIS ESSUIE GLACE AV AR
	0		LIQUIDE DE FREIN
23/11/2021	31.790	STELLANTIS &YOU FRANCE SAS	BALAIS ESSUIE GLACE AV
	0		REVISION
	0		BOITIER D ALLUMAGE RPLT
16/08/2021	22.566	CONTITRADE FRANCE	REMPLACEMENT PNEUS ETE