



BMW 3: [Redacted]

Vinnumber:	WBA6N91010FN04176	Versionname:	
First Registrationdate:	20/06/2022	Fiscalpower:	
Expertise Mileage:	115952	Power Kw:	
Bodytype:		Body colour:	Black
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2531
Fueltype:	Hybrid Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting LED		
Type of GPS:	GPS big screen color		
Type of Lining:	Lining artificial leather		
Type of climate control:	Autom climate control		

Limited Technical Inspection

Tyres

225/50/17/92 H				
Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/50 R 17 92 H
Tyre size FR				225/50 R 17 92 H
Tyre size RL				225/50 R 17 92 H
Tyre size RR				225/50 R 17 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal):	1
Number of charging cables (rapid charge):	1

Total cost ex VAT	954,46
Backrest cover FR, Scratch(es), Smart repair	116,69



Bumper F, Scratch(es), Acceptable 0,00



Bonnet, Scratch(es), Repair and paint (complete) 406,19



Alloy rim RL polished, Rust, Acceptable 0,00




Door FL, Scratch(es), Acceptable 0,00




Alloy rim FL polished, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), Acceptable 0,00



Tailgate / Boot, Scratch(es), Acceptable 0,00



Wing FR, Scratch(es), Acceptable 0,00



Door RR, Scratch(es), Acceptable 0,00



Door RR, Dent(s) and scratch(es), Acceptable 0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

431,58

