



Toyota PROACE ELECTRIC WORKER BEV Extra Range Cool 136pk Comfort Long Trekhaak PDC, Jul-22, 119,928 km



Memo



VIN	YARV1ZKXZGZ004396
Initial registration	19-07-2022
Initial Dutch Registration	19-07-2022
European Type Approval	e2*2007/46*0538*17
Mileage reading / hour counter reading	119,928 km 
Mileage Status:	Logical (NAP)
Automatic	Yes
Fuel	BEV Electric
Cylinders / Engine capacity	
Weight	2028 kg
Doors	5
Power capacity	100 kW
Emission code / Energy label	Z
Wheelbase	328
Loading space	
Load capacity	1027
RDW details	
Battery capacity	
Range	
Battery health	
Charging cables type	
AC/DC	
Battery purchase/rent	Unknown
Taxation	VAT (Grey number plate)
Colour	White
Country of registration	The Netherlands
Origin	Lease

Accessories fitted to vehicles

 Manually operated air conditioning	 Electronic Stability Program	 Start immobiliser
 ABS	 Electric windows front	 Tow bar
 Bluetooth telephone connection	 Lath to lath paneling / siding	 Two-seater bench
 Central locking remote control	 Parking sensors rear	 Floor plate
 Cruise control	 Sliding door right	 Heat reflecting glass

Accessories fitted to vehicles (stated by offerer, conditionally)

- | | | |
|--|--|---|
| <ul style="list-style-type: none"> • 2 zitplaatsen rechtsvoor • Airco • Armsteun voor • Band.sp.contr.syst. • BAS • Bestuurdersairbag • Bluetooth telefoonvoorb. • Buitensp. elektr. + verw. | <ul style="list-style-type: none"> • Connected services • Cruise control • DAB radio • ESP • Grootlichtassistent • Hill hold functie • Lendesteunen (verstelb.) • Multimedia-voorbereiding | <ul style="list-style-type: none"> • Oplaadmogelijkheid • Passagiersairbag • Stoel best. hoogte verst. • Stof/kunstlederen bekl. • Verstelbaar stuur • Volledig tussenschot • Zijschuifdeur rechts |
|--|--|---|



Comments

No remarks

Vehicle state

MOT due date	19-07-2026	Cambelt replaced		Charging cable for charging station 2 (7 pins)	Not present
Maintenance history	Not present	Number of keys	1	Charging cable for charging station 1 (5 pins)	Not present
Maintenance until CVO/COC	Not present	Navigation Medium	Not present	Charging cable for plug connection	Not present
		Vehicle location	On location Owner	Wheel locks	Not present



Tyres

Rim size	16"		
Wheel	Brand	Type	Tread depth
Front wheel left	Yokohama	All Season tyre	5 mm
Front wheel right	Yokohama	All Season tyre	6 mm
Rear wheel left	Vredestein	All Season tyre	5 mm
Rear wheel right	Vredestein	All Season tyre	5 mm

Spare wheel	n/a	n/a	n/a
Spare wheel in place			

Bodywork inspection			
Incident		Component	Observations
Unacceptable damage			
1		Contactsleutel	Missing part
2		Zijwand a l (bedr.w)	dent(s)
			
3		Zijwand v l (bedr.w)	dent(s)
			
			
4		Front bumper	stone impact
5		Schuifdeur r	scratch(es) , door ontstickeren
6		Dorpel r	scratch(es) , door ontstickeren
7		Tankklep	scratch(es) , door ontstickeren
8		Rear bumper	scratch(es)
			
9		Roof	various damage (see photo)
			
Comments			
No remarks			

Vendor