MACADAM









Toyota Corolla: Z316LZ

Vinnumber:	**SB1ZB3AE60E121622**	Versionname:	**Corolla 1.8 Hybrid 103kW Active Touring Sports CVT**
First Registrationdate:	**21/05/2024**	Fiscalpower:	
Expertise Mileage:	**61800**	Power Kw:	**72**
Bodytype:		Body colour	**Precious Silver metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Hybrid Petrol**	Parking lot	**1155**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Rear view camera	
GPS			
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 55 / 16 / 91 / V / Aluminium	6,2 mm	Vredestein	All season
	Right	205 / 55 / 16 / 91 / V / Aluminium	6,2 mm	Vredestein	All season
Rear	Left	205 / 55 / 16 / 91 / V / Aluminium	5,3 mm	Vredestein	All season
	Right	205 / 55 / 16 / 91 / V / Aluminium	5,0 mm	Vredestein	All season

Assistance equipment

Number of charging cables (rapid charge)	**0**

Service, Maintenance, Execute



Roof liner, Scratch(es), Replace




Outside rear-view mirror housing L, Scratch(es), Replace and paint




Bonnet, Dent(s) and scratch(es), Repair and paint (complete)





Door RR, Dent(s), Paintless dent repair




Roof pillar R, Dent(s), Repair and paint (complete)





Bumper R, Scratch(es), Repair and paint (complete)







Roof, Dent(s), Repair and paint (complete)






Onderhoudshistorie van: SB1ZB3AE60E121622

ALPHABET

Kenteken	Z316LZ
Merk Model	Toyota Corolla 1.8 Hybrid 103kW Active Touring Sports
Brandstofsoort	Benzine
Datum deel1	5/21/24

Datum reparatie	Kilometerstand	Reparatie omschrijving
6/5/26	47,329	Onderhoudsbeurt
6/5/26	47,329	Uitlijnen voor en achterwielen
6/5/26	47,329	Vervanging band
7/31/25	13,437	Onderhoudsbeurt
5/28/24	30	Vervanging band