


Vehicle details

VIN	KNACR811F P5049562	Brand	KIA	Maintenance date	-
Licence Plate		Model	Niro EV 64.8kWh DynamicLine 5d	Maintenance mileage	-
Registration date	30/05/2023	Year	2023	Exterior Color	Grey Metallic
Odometer	284 805 km	Engine size	-	Interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date 22/07/2026



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Vehicle charger	✓
Rear parcel shelf	✗
Wireless charger	✗

Technical Document

Remote key	✓
Sat Nav CD ROM Software	✓
Spare key	✗

Tyres

Pirelli 215/55/17 Summer 3.0 mm



Pirelli 215/55/17 Summer 3.0 mm




Pirelli 215/55/17 Summer 4.0 mm

Pirelli 215/55/17 Summer 4.0 mm

Exterior

4



Part	Door
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

5



Part	Door moulding
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Door moulding
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

7



Part	Door
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

9



Part	Step plate
Position	Front left
Damages	Dent & Chips
Severity	-
Repair mode	For info

11



Part	Step plate
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	For info

12



Part	Spoiler
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

14



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

15



Part	Bumper moulding
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

16



Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

17



Part	Door
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

18



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

19



Part	Step plate
Position	Back right
Damages	Dent & Chips
Severity	-
Repair mode	For info

20



Part	Step plate
Position	Front right
Damages	Dent & Chips
Severity	-
Repair mode	For info

21



Part	Wing
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

22



Part	Bonnet
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

23



Part	Bumper moulding
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Replace

Interior damage

1



●●●

Part	Rear parcel shelf
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

3



●

Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

8



●●●

Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

10



●●●

Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

13



●●

Part	Interior tailgate lining
Position	Up
Damages	Missing
Severity	-
Repair mode	Replace

Others

2



Part	Wireless charger
Position	-
Damages	Missing
Severity	-
Repair mode	For info