MACADAM










## Renault Trafic: VJB94B

| | | | |
|---|---|---|---|
| Vinnumber: | **VF1FL000565906642** | Versionname: | **Trafic T29 2.0 DCI Energy 88kW Comfort GB L2H1** |
| First Registrationdate: | **21/01/2021** | Fiscalpower: | |
| Expertise Mileage: | **130870** | Power Kw: | **88** |
| Bodytype: | | Body colour | **Blanc Glacier standaard** |
| Gearbox: | **MAN 6 VIT** | Paint type | **Opaque** |
| Transmission: | | Type of rims (mounted) | **Steel** |
| Fueltype: | **Diesel** | Parking lot | **910** |
| Number of seats | **2** | | |
| Type of rims (mounted) | **Steel** | | |
| Maintenance needed | **No** | | |

## Options

| | | | |
|---|---|---|---|
| Number of keys total | **2** | Rear parking sensors | |
| GPS | | Hook | |
| Manual climate control | | Sliding door right-side | |
| Radio multimedia | | Sliding door left-side | |

## Tyres

| Location | Position | Measures | Depth | Make | Type |
|---|---|---|---|---|---|
| Front | Left | 215 / 65 / 16 / 109 / T / Steel | 7,2 mm | Continental | All season |
| | Right | 215 / 65 / 16 / 109 / T / Steel | 7,1 mm | Continental | All season |
| Rear | Left | 215 / 65 / 16 / 109 / T / Steel | 8,8 mm | Continental | All season |
| | Right | 215 / 65 / 16 / 109 / T / Steel | 7,8 mm | Continental | All season |

## Assistance equipment

### Glove compartment lid, Scratch(es), Replace




### Gear shift lever cover, Broken, Replace



### Interior, Dirty, Cleaning





### Sliding door L, Bad repair, Repair and paint (complete)




**Bonnet, Stone chip(s), Repair and paint (complete)**









**Outside rear-view mirror housing R, Broken, Replace**





**Side wall RR, Bad repair, Repair and paint (complete)**




**Sliding door R, Bad repair, Repair and paint (complete)**




**Reflector, Missing, Replace**






**Bumper R, Scratch(es), Smart repair**










**Bumper corner RL, Scratch(es), Smart repair**






**Boot door panel RR, Dent(s), Repair and paint (complete)**





**Bodywork, Chemical polution, Polish**








# Onderhoudshistorie van: VF1FL000565906642

ALPHABET

| | |
|---|---|
| **Kenteken** | VJB94B |
| **Merk Model** | Renault Trafic T29 2.0 DCI Energy 88kW Comfort GB L2H1 |
| **Brandstofsoort** | Diesel |
| **Datum deel1** | 1/21/21 |

| Datum reparatie | Kilometerstand | Reparatie omschrijving |
|---|---|---|
| 10/13/26 | 130,159 | AdBlue pomp |
| 9/28/26 | 129,562 | Ruitenwisserblad(en) voorzijde |
| 7/30/26 | 128,241 | AdBlue pomp |
| 1/22/26 | 126,012 | APK |
| 1/22/26 | 126,012 | Fijnstofmeting |
| 11/1/25 | 0 | Accu |
| 10/23/25 | 118,024 | Vervanging band |
| 10/7/25 | 116,557 | Airco controle |
| 10/7/25 | 116,557 | Brandstoffilter |
| 10/7/25 | 116,557 | Luchtfilter |
| 10/7/25 | 116,557 | Onderhoudsbeurt |
| 10/7/25 | 116,557 | Remvloeistof |
| 10/7/25 | 116,557 | Ruitenwisserblad(en) achterzijde |
| 10/7/25 | 116,557 | Ruitenwisserblad(en) voorzijde |
| 10/7/25 | 116,557 | Vervanging band |
| 7/29/25 | 111,989 | Remschijf + blokken voor |
| 1/27/25 | 97,559 | APK |
| 1/27/25 | 97,559 | Spoorstangkogel |
| 1/27/25 | 97,559 | Uitlijnen voorwielen |
| 1/27/25 | 97,559 | Vervanging band |
| 6/4/24 | 75,201 | Brandstoffilter |
| 6/4/24 | 75,201 | Onderhoudsbeurt |
| 6/4/24 | 75,201 | Vervanging band |
| 1/25/24 | 60,282 | APK |
| 1/25/24 | 60,282 | Fijnstofmeting |
| 1/25/24 | 60,282 | Remblokken achterzijde |
| 1/25/24 | 60,282 | Remblokken voorzijde |
| 1/25/24 | 60,282 | Sensor olieniveau |
| 1/10/23 | 28,860 | Onderhoudsbeurt |
| 1/10/23 | 28,860 | Vervanging band |