

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	309972
License plate	2CQH417
Vehicle identification number	WBA7M910607L70153
Dossier	2021322018
Make	BMW 118d 100kW
Mileage	44754
First registration	17/10/2022
client availability date	07/04/2026
inspectionDate	15/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	Y
63	Wing Front Left // Painting	Y
83	Door Front Left // Painting	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	N
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

## Damage Pictures



Wheel Alloy Rear Left // Repair-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Painting-scratch




Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Windshield // Replace-glass damage



Interior Cleaning // Small-stain